


FCC ID # 0FV-PTM 1000-38
Channel 0


ATTEN 30dB VAVG 100 MKR -30.33dBm
RL 16.0dBm 10dB/ 38.60000GHz



CENTER 38.60000GHz SPAN 24.00MHz
*RBW 100kHz VBW 100kHz SWP 50.0ms

FCC ID# OPU-PTM1000-38
Channel 0


ATTEN 20dB VAVG 27 MKR -24.00dBm
RL 16.00dBm 10dB/



CENTER 38.6000GHZ SPAN 200.0MHZ
*RBW 100KHZ VBW 100KHZ SWP 50.0ms

FCC ID# OPU-PTM1000-38
Channel 6


ATTEEN 20DB VAVG 47 MKR -24.33DBM
RL 16.0DBM 38.6000GHZ 10DB/



CENTER 38.6000GHZ SPAN 400.0MHZ
*RBW 100KHZ VBW 100KHZ SWP 100MS

FCC ID# 2PU-PTM1000-38
CHANNEL 167


ATTEN 30dB VAVG 67 MKR -31.83dBm
RL 16.0dBm 10dB/



CENTER 40.00000GHZ SPAN 24.00MHZ
*RBW 100KHZ VBW 100KHZ SWP 50.0ms

FCC ID# OPV-PTM-1000
Channel 167


ATTEN 20dB VAVG 31 MKR -26.17dBm
RL 16.0dBm 10dB/



CENTER 40.0000GHZ SPAN 200.0MHz
*RBW 100kHz VBW 100kHz SWP 50.0ms

FCC ID # 0PU-PTM1000-38
Channel 167

ATTEN 20dB VAVG 66 MKR -26.17dBm
RL 16.0dBm 10dB/



CENTER 40.0000GHz SPAN 400.0MHz
*RBW 100kHz VBW 100kHz SWP 100ms