

⚠ DANGER



INVISIBLE LASER RADIATION.

Avoid direct eye exposure to the end of a fiber, fiber cord, or fiber pigtail.

The infrared light in fiber optics systems is invisible, but will cause serious injury to the eye, including blindness.



HIGH VOLTAGE AND CURRENT.

This device has a -48 vdc input (4 amps operating peak per feed).

Do not work on the system or connect/disconnect cables during lightning activity, rainy weather, or both.

Death or serious injury will result.

⚠ WARNING



RADIO FREQUENCY ENERGY.

Radio transmitter is ON when red light indicator on the back side of the radio is illuminated. Do not stand in front of the radio unit antenna while the radio is ON. Observe RF energy exposure and service interruption cautions in the product manuals. Serious bodily injury may result.



Read and understand operator's manual before using this equipment.

Failure to follow operating instructions could result in death or serious injury.

⚠ CAUTION



LIFTING HAZARD.

Recommended two person lift.



SERVICE AND WARRANTY.

Service by trained technicians only.
No owner/user serviceable parts.

Opening the radio unit or tampering with any of its seals voids all warranties.