

Class II Change Letter

Dated this 2006/4/25

FEDERAL COMMUNICATIONS COMMISSION
Authorization and Evaluation Division
7435 Oaklnd Mills Road
Columbia, MD 21046
U.S.A.

To whom it may concern,

We, Sporton International Inc., on behalf of **Globlink Technology Inc.**, would like to confirm that the product with FCC ID: OR710KEY910 has further modification as below:

1. Antenna change: from loop antenna to wire antenna with L5 matching impedance.
2. Capacitor C4 used on voltage part has been removed.
3. Add ON/OFF switch SW1.
4. The resistance of R5 is changed to 150 Ω , for LED.

Sincerely yours,

Signature :



Name/Title : Wayne Hsu

Company : Sporton International Inc.

Address : No. 52, Hwa Ya 1st Road.,
Kwei-Shan Hsiang, TaoYuan Hsien
Taiwan R.O.C.

Tel. No. : 886-3-3273456 ext 527

E-Mail : TCB@sporton.com.tw