


INTERTEK TESTING SERVICES

Report No.: HK11100126-1 Sample No.: 2/2

INTERTEK TESTING SERVICES

Report No.: HK11100126-1 Sample No.: 2/2



Maximum Output Power at Antenna terminal Plot – Pursuant to FCC Part 15 Section 15. <u>247</u> Requirement

(of)