

Report No.: 0307222
Model No.: 24062

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement


PLT: 17.60ms

-0.12dB

RB 3MHz# AT 10dB

RLV: 67.00dBuV

VB 3MHz



Tested By: LR
(Kevin Wong)

Date: 17/7/03

Checked By: [Signature]
(Anthony Chen)

Date: 17/7/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 60ms

F: 27.144900MHz

Report No.: 0307222
Model No.: 24062

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement


DLT: 17.58ms

-0.01dB

RB 3MHz# AT 10dB

RLV: 87.00dBuV

VB 3MHz



Tested By: LR
(Kenneth Wong)

Date: 17/7/03

Checked By: [Signature]
(Derek Chan)

Date: 17/7/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 30ms

F: 27.144900MHz

INTERTEK TESTING SERVICES

Report No.: 0307222
Model No.: 24062

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement


DLT: 1.44ms

-0.54dB

RB 3MHz# AT 10dB

ALV: 67.00dBuV

VB 3MHz



Tested By: KL
(Kevin Wong)

Date: 17/7/03

Checked By: [Signature]
(Anthony Chan)

Date: 17/7/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 30ms

F: 27.144900MHz

Report No.: 0307222
Model No.: 24062

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement


DLT: 420us

-0.19dB

RB 3MHz# AT 10dB

ALV: 87.00dBuV

VB 3MHz



Tested By: LA
(Kenne R Wong)

Date: 17/7/03

Checked By: [Signature]
(Anthony Chan)

Date: 17/7/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 30ms

F: 27.144900MHz