

INTERTEK TESTING SERVICES

Report No.: 0610155  
Model No.: 73846  
Sample No.: 2/2




Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

MKR 49.0 KHz  
-37.19 dB

REF -20.0 dBm AT 10 dB

PEAK  
LOG  
10  
dB/



MA SB  
SC FS  
CORR

Tested By: [Signature]  
(Chan Ho 'm)

Date: 26/5/2006

Checked By: [Signature]  
(Gary Li)

Date: 29/5/2006

Test Result: Pass / Fail / NA

START 49.8100 MHz

STOP 49.9100 MHz

#RES BW 1.0 KHz

#VBW 3 MHz

#SWP 1.00 sec