

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP

INTERNAL PHOTOS



Figure 1. Top View - Cover Removed

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP



Figure 2. Internal PCB – Top Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 3. Internal PCB – Bottom Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP



Figure 4. Radio Module – Top Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 5. Radio Module – Bottom Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 6. Radio Module - Opened

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP



Figure 7. Inside of Radio Module – Top Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 8. Inside of Radio Module – Bottom Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 9. Unpopulated PCB Top Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 10. PCB Bottom Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 11. Top of Enclosure – Bottom Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Certification
OU507APFH-AP
24-0230
September 30, 2024
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 12. Bottom of Enclosure – Top Side