

APPENDIX 3: Photographs of test setup

Radiated Emission **(DR Antenna)**




Photo 1




Photo 2

Radiated Emission
(InF Antenna)




Photo 1




Photo 2

Worst Case Position


LF Antenna(DR Antenna)

Below 30MHz: X-axis

Above 30MHz

Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



ECU

Below 30MHz: X-axis

Above 30MHz

Horizontal: Z-axis / Vertical: Z-axis

X-axis



Y-axis



Z-axis



UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position


LF Antenna(InF Antenna)

Below 30MHz: X-axis

Above 30MHz

Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



ECU

Below 30MHz: X-axis

Above 30MHz

Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124