


9. SETUP PHOTOS


RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION









RADIATED RF MEASUREMENT SETUP WITH AC/DC ADAPTER CONFIGURATION, X POSITION (WORST CASE)





POWER-LINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT

Page 31 of 31