


8. SETUP PHOTOS

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION



SLIDE OUT X-AXIS WITH CHARGER PHOTO



SLIDE OUT Y-AXIS PHOTO



SLIDE OUT Y-AXIS WITH CHARGER PHOTO




SLIDE OUT Z-AXIS PHOTO




SLIDE OUT Z-AXIS WITH CHARGER PHOTO




RADIATED RF MEASUREMENT SETUP FOR RECEIVER MODE



RADIATED EMISSIONS BACK PHOTO



AC MAINS LINE CONDUCTED EMISSION





END OF REPORT