

Tune Up Procedure

07/19/2023

Head Office:

Barrett Communications Pty Ltd 47 Discovery Drive, Bibra Lake, WA, 6163 AUSTRALIA Tel: +61 8 9434 1700 Fax: +61 8 9418 6757 info@barrettcommunications.com.au www.barrettcommunications.com.au

TO WHOM IT MAY CONCERN

This letter is to certify that the Barrett PRC-4090 HF Transceiver requires no tune up procedure as the unit contains a fully automatic antenna tuner that re-tunes each time the frequency or channel is changed.

Dated this _	19	Day of	July	20 23	
		OMMUN Lindy Aust	RALIA S		
Ву:			David Archer		
Signature			Printed		
Title:	Techni	cal Manager			
Applicant:	Barrett	Communicatio	ns Pty Ltd		