



**360 Industrial Pkwy South Unit#1&2  
Aurora, Ont. Canada L4G 3V7  
Phone: (905) 726-3444 Fax: (905) 726-4233  
Email [mct@globalserve.net](mailto:mct@globalserve.net)**

Nov. 14, 2002

ATCB  
6731 Whittier Ave.  
McLean, VA22101

Reference: FCC ID: OW5BST800

Dear Sirs,

In response to your request regarding tune up procedures for the devices bearing the above mentioned FCC type approval numbers. Please be informed that tuning of this device is done at the manufacturer's premises. End users must return the device to MCT Inc. for tuning.

Sincerely,

Tom Vagenas  
MCT, Inc.