



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:29:03

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:29:14

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:29:39

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:29:50

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:30:15

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:30:27

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:30:59

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:31:11

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:31:29

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:31:40

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:31:58

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:32:09

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:32:39

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:32:50

Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:33:08


Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 1.JUN.2021 23:33:20




### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:33:40

### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:33:52

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:34:23

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:34:35

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:34:55

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:35:06

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:35:30


### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)



Date: 1.JUN.2021 23:35:41




### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:36:54

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:37:05

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:37:30

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:37:41

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:38:15


### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 1.JUN.2021 23:38:27




### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:38:51

### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:39:03

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:39:27

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:39:39

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:40:03

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:40:14

Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:40:32


Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)



Date: 1.JUN.2021 23:40:43




Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:41:37

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:41:48

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:42:06

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:42:18

### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:42:35


### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 1.JUN.2021 23:42:47




Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:43:08

Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:43:19

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:43:40

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:43:52

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:44:09


### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 1.JUN.2021 23:44:21




### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:45:19

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:45:30

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:45:50

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:46:02

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:46:32

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:46:44

Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:47:08


Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 1.JUN.2021 23:47:20




### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:47:44

### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:47:56

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:48:27

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:48:38

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:49:06

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:49:17

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:49:45

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 1.JUN.2021 23:49:56

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:50:28

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 1.JUN.2021 23:50:43






### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:52:17

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 1.JUN.2021 23:52:28



















### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:56:47


### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 1.JUN.2021 23:56:58




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:57:25


### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)



Date: 1.JUN.2021 23:57:36




### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 1.JUN.2021 23:58:29

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 1.JUN.2021 23:58:41

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 1.JUN.2021 23:59:04


### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)



Date: 1.JUN.2021 23:59:16




### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:00:10

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 2.JUN.2021 00:00:22

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:00:50

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 2.JUN.2021 00:01:01

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:01:25


Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 2.JUN.2021 00:01:37




### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:02:01

### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 2.JUN.2021 00:02:13

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:02:44

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 2.JUN.2021 00:02:55

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:03:20

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 2.JUN.2021 00:03:31

### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:03:55


### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 2.JUN.2021 00:04:07




Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:05:01

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:05:12








### Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:06:35

### Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:06:46

### Band 12\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:07:07


### Band 12\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 2.JUN.2021 00:07:19




### Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:08:15

### Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:08:27








### Band 12\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:10:26

### Band 12\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:10:37






### Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 18.JUL.2021 19:59:05

### Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_4(793MHz-805MHz)




Date: 18.JUL.2021 19:59:40

### Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_5(1559MHz-1610MHz)




Date: 18.JUL.2021 20:00:24

### Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:11:37

Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)



Date: 2.JUN.2021 00:11:48


Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_3(763MHz-775MHz)



Date: 18.JUL.2021 20:01:37




### Band 13\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:12:09

### Band 13\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:12:21

Band 13\_5 MHz\_High\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 18.JUL.2021 20:03:17

Band 13\_5 MHz\_High\_QPSK\_RB25#0\_4(793MHz-805MHz)




Date: 18.JUL.2021 20:03:35

Band 13\_5 MHz\_High\_QPSK\_RB25#0\_5(1559MHz-1610MHz)



Date: 18.JUL.2021 20:04:10


Band 13\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:12:43




Band 13\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 2.JUN.2021 00:12:54


Band 13\_10 MHz\_Middle\_QPSK\_RB50#0\_3(763MHz-775MHz)



Date: 18.JUL.2021 20:06:22




### Band 25\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:13:21

### Band 25\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:13:33

### Band 25\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:13:50

### Band 25\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:14:02

### Band 25\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:14:23

### Band 25\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:14:34

### Band 25\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:14:58

### Band 25\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:15:10

### Band 25\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:15:28

### Band 25\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:15:39

### Band 25\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:16:00


### Band 25\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 2.JUN.2021 00:16:12




### Band 25\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:16:33

### Band 25\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:16:44

### Band 25\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:17:05

### Band 25\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:17:17

### Band 25\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:17:34

### Band 25\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:17:46

### Band 25\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:18:12

### Band 25\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:18:24

### Band 25\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:18:47

### Band 25\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:18:59

### Band 25\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:19:19

### Band 25\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:19:30

### Band 25\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:19:58

### Band 25\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:20:09

Band 25\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:20:37


Band 25\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 2.JUN.2021 00:20:50




### Band 25\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:21:17

### Band 25\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:21:30

### Band 25\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:21:58

### Band 25\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:22:09

### Band 25\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:22:34

### Band 25\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:22:45

Band 25\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:23:10

Band 25\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 2.JUN.2021 00:23:21

### Band 26\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:23:50

### Band 26\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:24:01

### Band 26\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:24:22

### Band 26\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:24:34

### Band 26\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:24:52

### Band 26\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:25:03

### Band 26\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:25:24


### Band 26\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 2.JUN.2021 00:25:36




### Band 26\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:25:53

### Band 26\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:26:05

### Band 26\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:26:26

### Band 26\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:26:37

### Band 26\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:26:58

### Band 26\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:27:10

### Band 26\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:27:31

### Band 26\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:27:43

Band 26\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:28:04

Band 26\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:28:15

### Band 26\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:28:42

### Band 26\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:28:53

Band 26\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:29:16

Band 26\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:29:29

### Band 26\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:29:52


### Band 26\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 2.JUN.2021 00:30:04




### Band 26\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 2.JUN.2021 00:30:35

### Band 26\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-10GHz)




Date: 2.JUN.2021 00:30:46

Band 26\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 2.JUN.2021 00:31:11

Band 26\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-10GHz)



Date: 2.JUN.2021 00:31:22

