



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.JUN.2021 01:42:30

### Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.JUN.2021 00:33:06

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.JUN.2021 00:33:25

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.JUN.2021 00:33:42

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.JUN.2021 00:34:15

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.JUN.2021 00:34:33

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 2.JUN.2021 00:34:51

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 2.JUN.2021 00:35:09

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.JUN.2021 00:35:39

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.JUN.2021 00:35:57

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.JUN.2021 00:36:15

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.JUN.2021 00:36:33

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.JUN.2021 00:37:05

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.JUN.2021 00:37:25

### Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 2.JUN.2021 00:37:45


### Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 2.JUN.2021 00:38:05




### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.JUN.2021 00:38:42

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.JUN.2021 00:39:06

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.JUN.2021 00:39:35

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.JUN.2021 00:39:59

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.JUN.2021 00:40:34

### Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.JUN.2021 00:41:01

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 2.JUN.2021 00:41:27

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 2.JUN.2021 00:41:51

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.JUN.2021 00:42:16

### Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.JUN.2021 00:42:36

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.JUN.2021 00:42:55

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.JUN.2021 00:43:16

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.JUN.2021 00:43:38

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.JUN.2021 00:43:55

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 2.JUN.2021 00:44:14


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 2.JUN.2021 00:44:31




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.JUN.2021 00:44:53

### Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.JUN.2021 00:45:14

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.JUN.2021 00:45:36

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.JUN.2021 00:45:53

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.JUN.2021 00:46:17

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.JUN.2021 00:46:40

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 2.JUN.2021 00:47:01

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 2.JUN.2021 00:47:21

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.JUN.2021 00:47:49

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.JUN.2021 00:48:17

### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.JUN.2021 00:48:42

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.JUN.2021 00:49:06

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.JUN.2021 00:49:35

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.JUN.2021 00:50:02

### Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 2.JUN.2021 00:50:28


### Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 2.JUN.2021 00:50:52




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.JUN.2021 00:51:22

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.JUN.2021 00:51:40

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.JUN.2021 00:51:58

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.JUN.2021 00:52:19

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.JUN.2021 00:52:49

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.JUN.2021 00:53:07

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 2.JUN.2021 00:53:25

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 2.JUN.2021 00:53:43

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 6.JUN.2021 15:33:42

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 9.SEP.2021 18:02:17

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 6.JUN.2021 15:31:25

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.JUN.2021 00:55:06

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.JUN.2021 00:55:42

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.JUN.2021 00:56:02

### Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 2.JUN.2021 00:56:22


### Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 2.JUN.2021 00:56:45




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.JUN.2021 00:57:09

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.JUN.2021 00:57:27

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.JUN.2021 00:57:45

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.JUN.2021 00:58:03

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.JUN.2021 00:58:27

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.JUN.2021 00:58:47

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 2.JUN.2021 00:59:10

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 2.JUN.2021 00:59:30

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.JUN.2021 00:59:59

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.JUN.2021 01:00:23

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.JUN.2021 01:00:48

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.JUN.2021 01:01:13

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.JUN.2021 01:01:41

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.JUN.2021 01:02:06

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 2.JUN.2021 01:02:31


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 2.JUN.2021 01:02:55




### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.JUN.2021 01:03:21

### Band 12\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.JUN.2021 01:03:42

### Band 12\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.JUN.2021 01:04:00

### Band 12\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.JUN.2021 01:04:21

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.JUN.2021 01:04:43

### Band 12\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.JUN.2021 01:05:00

### Band 12\_3 MHz\_High\_QPSK\_RB15#0




Date: 2.JUN.2021 01:05:19

### Band 12\_3 MHz\_High\_16QAM\_RB15#0




Date: 2.JUN.2021 01:05:36

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.JUN.2021 01:06:01

### Band 12\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.JUN.2021 01:06:22

### Band 12\_5 MHz\_High\_QPSK\_RB25#0




Date: 6.JUN.2021 15:30:07

### Band 12\_5 MHz\_High\_16QAM\_RB25#0




Date: 6.JUN.2021 15:29:21

### Band 12\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.JUN.2021 01:07:22

### Band 12\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.JUN.2021 01:07:45

### Band 12\_10 MHz\_High\_QPSK\_RB50#0



Date: 2.JUN.2021 01:08:06


### Band 12\_10 MHz\_High\_16QAM\_RB50#0



Date: 2.JUN.2021 01:08:26




### Band 13\_5 MHz\_Low\_QPSK\_RB25#0




Date: 6.JUN.2021 15:37:12

### Band 13\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.JUN.2021 02:36:11

### Band 13\_5 MHz\_High\_QPSK\_RB25#0




Date: 6.JUN.2021 15:38:46

### Band 13\_5 MHz\_High\_16QAM\_RB25#0




Date: 6.JUN.2021 15:39:28

### Band 13\_10 MHz\_Low\_QPSK\_RB50#0




Date: 18.JUL.2021 19:55:28

### Band 13\_10 MHz\_Low\_16QAM\_RB50#0




Date: 18.JUL.2021 19:56:15

### Band 13\_10 MHz\_High\_QPSK\_RB50#0




Date: 18.JUL.2021 19:57:13

### Band 13\_10 MHz\_High\_16QAM\_RB50#0




Date: 18.JUL.2021 19:56:40

### Band 25\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.JUN.2021 01:20:55

### Band 25\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.JUN.2021 01:21:13

### Band 25\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.JUN.2021 01:21:35

### Band 25\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.JUN.2021 01:21:55

### Band 25\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.JUN.2021 01:22:17

### Band 25\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.JUN.2021 01:22:35

### Band 25\_3 MHz\_High\_QPSK\_RB15#0



Date: 2.JUN.2021 01:22:53


### Band 25\_3 MHz\_High\_16QAM\_RB15#0



Date: 2.JUN.2021 01:23:11




### Band 25\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.JUN.2021 01:23:33

### Band 25\_5 MHz\_Low\_16QAM\_RB25#0




Date: 2.JUN.2021 01:23:50

### Band 25\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.JUN.2021 01:24:09

### Band 25\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.JUN.2021 01:24:30

### Band 25\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.JUN.2021 01:24:54

### Band 25\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.JUN.2021 01:25:17

### Band 25\_10 MHz\_High\_QPSK\_RB50#0




Date: 2.JUN.2021 01:25:37

### Band 25\_10 MHz\_High\_16QAM\_RB50#0




Date: 2.JUN.2021 01:25:57

### Band 25\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.JUN.2021 01:26:26

### Band 25\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.JUN.2021 01:26:50

### Band 25\_15 MHz\_High\_QPSK\_RB75#0




Date: 2.JUN.2021 01:27:17

### Band 25\_15 MHz\_High\_16QAM\_RB75#0




Date: 2.JUN.2021 01:27:43

### Band 25\_20 MHz\_Low\_QPSK\_RB100#0




Date: 2.JUN.2021 01:28:11

### Band 25\_20 MHz\_Low\_16QAM\_RB100#0




Date: 2.JUN.2021 01:28:39

### Band 25\_20 MHz\_High\_QPSK\_RB100#0



Date: 2.JUN.2021 01:29:04


### Band 25\_20 MHz\_High\_16QAM\_RB100#0



Date: 2.JUN.2021 01:29:28




### Band 26\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 2.JUN.2021 01:30:02

### Band 26\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 2.JUN.2021 01:30:19

### Band 26\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 2.JUN.2021 01:30:41

### Band 26\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 2.JUN.2021 01:31:02

### Band 26\_3 MHz\_Low\_QPSK\_RB15#0




Date: 2.JUN.2021 01:31:23

### Band 26\_3 MHz\_Low\_16QAM\_RB15#0




Date: 2.JUN.2021 01:31:41

### Band 26\_3 MHz\_High\_QPSK\_RB15#0




Date: 2.JUN.2021 01:32:00

### Band 26\_3 MHz\_High\_16QAM\_RB15#0




Date: 2.JUN.2021 01:32:17

### Band 26\_5 MHz\_Low\_QPSK\_RB25#0




Date: 2.JUN.2021 01:32:42

### Band 26\_5 MHz\_Low\_16QAM\_RB25#0




Date: 6.JUN.2021 15:26:49

### Band 26\_5 MHz\_High\_QPSK\_RB25#0




Date: 2.JUN.2021 01:33:18

### Band 26\_5 MHz\_High\_16QAM\_RB25#0




Date: 2.JUN.2021 01:33:39

### Band 26\_10 MHz\_Low\_QPSK\_RB50#0




Date: 2.JUN.2021 01:34:03

### Band 26\_10 MHz\_Low\_16QAM\_RB50#0




Date: 2.JUN.2021 01:34:23

### Band 26\_10 MHz\_High\_QPSK\_RB50#0



Date: 2.JUN.2021 01:34:44


### Band 26\_10 MHz\_High\_16QAM\_RB50#0



Date: 2.JUN.2021 01:35:03




### Band 26\_15 MHz\_Low\_QPSK\_RB75#0




Date: 2.JUN.2021 01:35:32

### Band 26\_15 MHz\_Low\_16QAM\_RB75#0




Date: 2.JUN.2021 01:35:56

### Band 26\_15 MHz\_High\_QPSK\_RB75#0



Date: 2.JUN.2021 01:36:22

### Band 26\_15 MHz\_High\_16QAM\_RB75#0



Date: 2.JUN.2021 01:36:46