



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:53:12

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:53:23

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:53:44

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:53:55

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:54:11

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:54:22

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:54:47

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:54:58

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:55:18

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:55:29

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:55:45

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:55:56

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:56:18

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:56:29

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:56:46

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:56:57

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:57:17

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:57:27

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:58:44

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:58:55

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:59:14

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:59:25

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 18:59:47

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 18.MAY.2021 18:59:58

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:14:09

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:14:19

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:14:46

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:14:57

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:15:20

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:15:31

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:25:31

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:25:42

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:26:08

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:26:19

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:26:43

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:26:53

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:27:13

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:27:24

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:27:41

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:27:52

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:28:12

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:28:22

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:32:09

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:32:28

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:32:49

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:33:00

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:33:17

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:33:28

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:38:22

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:38:33

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:38:50

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:39:00

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:39:21

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:39:31

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:41:41

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:41:52

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:42:11

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:42:22

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:42:41

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:42:52

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:44:38

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:44:49

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:45:15

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:45:26

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:45:50

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:46:00

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:48:07

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:48:18

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:48:41

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:48:52

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:49:15

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 18.MAY.2021 19:49:26

Band 5/Band 26(Part 22H) _1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:50:54

Band 5/Band 26(Part 22H) _1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 18.MAY.2021 19:51:05

Band 5/Band 26(Part 22H) _1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:51:25

Band 5/Band 26(Part 22H) _1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 18.MAY.2021 19:51:36

Band 5/Band 26(Part 22H) _1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:51:53

Band 5/Band 26(Part 22H) _1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 18.MAY.2021 19:52:03

Band 5/Band 26(Part 22H) _3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:56:37

Band 5/Band 26(Part 22H) _3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 18.MAY.2021 19:56:47

Band 5/Band 26(Part 22H)_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:57:08

Band 5/Band 26(Part 22H)_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 18.MAY.2021 19:57:18

Band 5/Band 26(Part 22H) _3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:57:36

Band 5/Band 26(Part 22H) _3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 18.MAY.2021 19:57:47

Band 5/Band 26(Part 22H) _5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 19:59:51

Band 5/Band 26(Part 22H) _5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:00:01

Band 5/Band 26(Part 22H) _5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:00:18

Band 5/Band 26(Part 22H) _5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:00:29

Band 5/Band 26(Part 22H) _5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:00:48

Band 5/Band 26(Part 22H) _5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:01:02

Band 5/Band 26(Part 22H) _10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:03:05

Band 5/Band 26(Part 22H) _10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:03:16

Band 5/Band 26(Part 22H) _10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:03:35

Band 5/Band 26(Part 22H) _10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:03:45

Band 5/Band 26(Part 22H) _10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:04:08

Band 5/Band 26(Part 22H) _10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:04:18

Band 26(Part 90S) _15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.AUG.2021 11:34:12

Band 26(Part 90S) _15 MHz_Low_QPSK_RB75#0_2(1GHz-10GHz)




Date: 17.AUG.2021 11:34:24

Band 26(Part 90S) _15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.AUG.2021 11:34:51

Band 26(Part 90S) _15 MHz_Middle_QPSK_RB75#0_2(1GHz-10GHz)




Date: 17.AUG.2021 11:35:02

Band 26(Part 90S) _15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.AUG.2021 11:35:26

Band 26(Part 90S) _15 MHz_High_QPSK_RB75#0_2(1GHz-10GHz)




Date: 17.AUG.2021 11:35:38

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:06:12

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:06:23

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:06:40

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:06:51

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:07:08

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:07:18

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:07:44

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:07:55

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:08:16

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:08:26

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:08:49

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:08:59

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:09:30

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:09:40

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:10:07

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:10:18

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:10:50

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:11:01

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:11:28

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:11:39

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:12:02

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:12:13

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:12:37

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 18.MAY.2021 20:12:47

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:15:47

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:15:58

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:16:15

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:16:26

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:16:50

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:17:01

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:19:33

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:19:43

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:20:00

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:20:11

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:20:28

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:20:38

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:21:02

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:21:12

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:21:32

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:21:43

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:22:03

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:22:17

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:24:13

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:24:24

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:24:43

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:24:54

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 6.AUG.2021 01:47:18

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:25:23

Band 13_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:26:54

Band 13_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:27:05

Band 13_5 MHz_Low_QPSK_RB25#0_3(763MHz-775MHz)




Date: 6.AUG.2021 00:53:27

Band 13_5 MHz_Low_QPSK_RB25#0_4(793MHz-805MHz)




Date: 6.AUG.2021 01:37:47

Band 13_5 MHz_Low_QPSK_RB25#0_5(1559MHz-1610MHz)




Date: 6.AUG.2021 00:56:38

Band 13_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:27:22

Band 13_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:27:32

Band 13_5 MHz_Middle_QPSK_RB25#0_3(763MHz-775MHz)




Date: 6.AUG.2021 01:20:51

Band 13_5 MHz_Middle_QPSK_RB25#0_4(793MHz-805MHz)




Date: 6.AUG.2021 01:38:57

Band 13_5 MHz_Middle_QPSK_RB25#0_5(1559MHz-1610MHz)




Date: 6.AUG.2021 01:19:43

Band 13_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:27:52

Band 13_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:28:03

Band 13_5 MHz_High_QPSK_RB25#0_3(763MHz-775MHz)




Date: 6.AUG.2021 01:11:10

Band 13_5 MHz_High_QPSK_RB25#0_4(793MHz-805MHz)




Date: 6.AUG.2021 01:40:15

Band 13_5 MHz_High_QPSK_RB25#0_5(1559MHz-1610MHz)




Date: 6.AUG.2021 01:44:36

Band 13_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:28:24

Band 13_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 18.MAY.2021 20:28:35

Band 13_10 MHz_Middle_QPSK_RB50#0_3(763MHz-775MHz)




Date: 6.AUG.2021 01:42:49

Band 13_10 MHz_Middle_QPSK_RB50#0_4(793MHz-805MHz)




Date: 6.AUG.2021 01:42:11

Band 13_10 MHz_Middle_QPSK_RB50#0_5(1559MHz-1610MHz)




Date: 6.AUG.2021 01:16:49

Band 25_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:29:05

Band 25_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:29:15

Band 25_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:29:32

Band 25_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:29:43

Band 25_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:30:00

Band 25_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:30:11

Band 25_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:30:31

Band 25_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:30:41

Band 25_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:31:02

Band 25_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:31:17

Band 25_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:31:33

Band 25_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:31:44

Band 25_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:32:04

Band 25_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:32:15

Band 25_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:32:32

Band 25_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:32:46

Band 25_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:33:06

Band 25_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:33:16

Band 25_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:33:39

Band 25_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:33:49

Band 25_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:34:09

Band 25_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:34:19

Band 25_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:34:38

Band 25_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:34:49

Band 25_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:35:16

Band 25_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:35:27

Band 25_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:35:50

Band 25_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:36:01

Band 25_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:36:24

Band 25_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:36:34

Band 25_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:37:02

Band 25_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:37:12

Band 25_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:37:36

Band 25_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:37:46

Band 25_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 18.MAY.2021 20:38:10

Band 25_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 18.MAY.2021 20:38:21

Band 26(Part 90S) _1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.AUG.2021 10:30:20

Band 26(Part 90S) _1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.AUG.2021 10:30:32

Band 26(Part 90S) _1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.AUG.2021 10:30:50

Band 26(Part 90S) _1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.AUG.2021 10:31:01

Band 26(Part 90S)_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.AUG.2021 10:31:52

Band 26(Part 90S)_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.AUG.2021 10:32:03

Band 26(Part 90S) _3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.AUG.2021 10:32:21

Band 26(Part 90S) _3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.AUG.2021 10:32:32

Band 26(Part 90S)_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.AUG.2021 10:32:50

Band 26(Part 90S)_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.AUG.2021 10:33:01

Band 26(Part 90S) _5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.AUG.2021 10:33:20

Band 26(Part 90S) _5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.AUG.2021 10:33:31

Band 26(Part 90S) _5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.AUG.2021 10:33:52

Band 26(Part 90S) _5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.AUG.2021 10:34:04

Band 26(Part 90S) _10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)



Date: 17.AUG.2021 10:34:54

Band 26(Part 90S) _10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)



Date: 17.AUG.2021 10:35:05