



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2021 22:19:57

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2021 19:45:47

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2021 19:46:09

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2021 19:46:29

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2021 19:47:02

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2021 19:47:19

Band 2_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2021 19:47:38

Band 2_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2021 19:47:55

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 19:48:25

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 19:48:46

Band 2_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 19:49:07

Band 2_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 19:49:28

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 19:50:00

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 19:50:20

Band 2_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 19:50:41

Band 2_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 19:51:00

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2021 19:51:37

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 4.NOV.2021 19:52:01

Band 2_15 MHz_High_QPSK_RB75#0




Date: 4.NOV.2021 19:52:27

Band 2_15 MHz_High_16QAM_RB75#0




Date: 4.NOV.2021 19:52:51

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 4.NOV.2021 19:53:25

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 4.NOV.2021 22:21:22

Band 2_20 MHz_High_QPSK_RB100#0




Date: 4.NOV.2021 19:54:15

Band 2_20 MHz_High_16QAM_RB100#0




Date: 4.NOV.2021 19:54:39

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2021 19:55:04

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2021 22:22:49

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2021 19:55:40

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2021 19:55:58

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2021 19:56:19

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2021 19:56:37

Band 4_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2021 19:56:55

Band 4_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2021 19:57:13

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 19:57:34

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 19:57:52

Band 4_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 19:58:11

Band 4_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 19:58:28

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 19:58:53

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 19:59:13

Band 4_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 19:59:33

Band 4_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 19:59:53

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2021 20:00:25

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 4.NOV.2021 20:00:49

Band 4_15 MHz_High_QPSK_RB75#0




Date: 4.NOV.2021 20:01:15

Band 4_15 MHz_High_16QAM_RB75#0




Date: 4.NOV.2021 20:01:39

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 4.NOV.2021 20:02:07

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 4.NOV.2021 20:02:32

Band 4_20 MHz_High_QPSK_RB100#0




Date: 4.NOV.2021 20:02:57

Band 4_20 MHz_High_16QAM_RB100#0




Date: 4.NOV.2021 20:03:21

Band 5& Band 26(Part 22H)_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2021 20:03:51

Band 5& Band 26(Part 22H)_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2021 22:24:00

Band 5& Band 26(Part 22H)_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2021 20:04:30

Band 5& Band 26(Part 22H)_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2021 20:04:48

Band 5& Band 26(Part 22H)_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2021 20:05:18

Band 5& Band 26(Part 22H)_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2021 20:05:35

Band 5& Band 26(Part 22H)_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2021 20:05:54

Band 5& Band 26(Part 22H)_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2021 20:06:11

Band 5& Band 26(Part 22H)_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 22:25:23

Band 5& Band 26(Part 22H)_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 20:06:59

Band 5& Band 26(Part 22H)_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 22:26:08

Band 5& Band 26(Part 22H)_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 22:26:28

Band 5& Band 26(Part 22H)_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 20:08:07

Band 5& Band 26(Part 22H)_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 20:08:27

Band 5& Band 26(Part 22H)_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 20:08:51

Band 5& Band 26(Part 22H)_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 20:09:11

Band 26(Part 22H) _15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2021 21:20:40

Band 26(Part 22H) _15 MHz_Low_16QAM_RB75#0




Date: 4.NOV.2021 21:21:04

Band 26(Part 22H) _15 MHz_High_QPSK_RB75#0




Date: 4.NOV.2021 21:21:29

Band 26(Part 22H) _15 MHz_High_16QAM_RB75#0




Date: 4.NOV.2021 21:21:53

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 20:09:35

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 20:09:55

Band 7_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 20:10:14

Band 7_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 20:10:32

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 20:10:56

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 20:11:15

Band 7_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 20:11:36

Band 7_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 20:11:56

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2021 20:12:24

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 4.NOV.2021 20:12:52

Band 7_15 MHz_High_QPSK_RB75#0




Date: 4.NOV.2021 20:13:17

Band 7_15 MHz_High_16QAM_RB75#0




Date: 4.NOV.2021 20:13:44

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 4.NOV.2021 22:28:01

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 4.NOV.2021 20:14:37

Band 7_20 MHz_High_QPSK_RB100#0




Date: 4.NOV.2021 20:15:02

Band 7_20 MHz_High_16QAM_RB100#0




Date: 4.NOV.2021 20:15:26

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2021 20:15:55

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2021 20:16:16

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2021 20:16:34

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2021 20:16:52

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2021 22:30:09

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2021 20:17:31

Band 12_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2021 20:17:49

Band 12_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2021 20:18:07

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 22:31:34

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 20:18:49

Band 12_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 20:19:08

Band 12_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 22:32:29

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 22:34:59

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 20:20:12

Band 12_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 20:20:33

Band 12_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 20:20:55

Band 13_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 22:36:11

Band 13_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 20:21:44

Band 13_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 20:22:02

Band 13_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 20:22:20

Band 13_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 22:38:22

Band 13_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 22:39:49

Band 13_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 22:40:52

Band 13_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 22:40:21

Band 25_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2021 20:52:41

Band 25_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2021 20:53:01

Band 25_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2021 20:53:23

Band 25_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2021 20:53:44

Band 25_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2021 20:54:05

Band 25_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2021 20:54:23

Band 25_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2021 20:54:44

Band 25_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2021 20:55:02

Band 25_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 20:55:24

Band 25_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 20:55:41

Band 25_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 20:56:00

Band 25_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 20:56:17

Band 25_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 22:42:37

Band 25_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 22:43:14

Band 25_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 20:57:20

Band 25_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 20:57:40

Band 25_15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2021 22:45:12

Band 25_15 MHz_Low_16QAM_RB75#0




Date: 4.NOV.2021 20:58:33

Band 25_15 MHz_High_QPSK_RB75#0




Date: 4.NOV.2021 20:58:58

Band 25_15 MHz_High_16QAM_RB75#0




Date: 4.NOV.2021 20:59:22

Band 25_20 MHz_Low_QPSK_RB100#0




Date: 4.NOV.2021 20:59:51

Band 25_20 MHz_Low_16QAM_RB100#0




Date: 4.NOV.2021 21:00:15

Band 25_20 MHz_High_QPSK_RB100#0




Date: 4.NOV.2021 21:00:40

Band 25_20 MHz_High_16QAM_RB100#0




Date: 4.NOV.2021 21:01:04

Band 26(Part 90S) _1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2021 21:59:22

Band 26(Part 90S) _1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2021 22:06:24

Band 26(Part 90S)_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2021 22:07:57

Band 26(Part 90S)_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2021 22:08:20

Band 26(Part 90S)_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2021 22:09:15

Band 26(Part 90S)_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2021 22:09:32

Band 26(Part 90S) _3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2021 22:10:11

Band 26(Part 90S) _3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2021 22:10:30

Band 26(Part 90S) _5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 22:13:37

Band 26(Part 90S) _5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 22:14:13

Band 26(Part 90S) _5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 22:15:07

Band 26(Part 90S) _5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 22:16:23

Band 26(Part 90S)_10 MHz_QPSK_RB50#0



Date: 4.NOV.2021 22:16:58

Band 26(Part 90S)_10 MHz_16QAM_RB50#0



Date: 4.NOV.2021 22:17:21