


Annex C


Out of Band Emissions



Uplink_1710 - 1755 MHz_CDMA_lower




Uplink_1710 - 1755 MHz_CDMA_upper






Uplink_1850 - 1910 MHz_CDMA_lower




Uplink_1850 - 1910 MHz_CDMA_upper






Uplink_704 - 716 MHz_CDMA_lower




Uplink_704 - 716 MHz_CDMA_upper






Uplink_776 - 787 MHz_CDMA_lower




Uplink_776 - 787 MHz_CDMA_upper






Uplink_824 - 849 MHz_CDMA_lower




Uplink_824 - 849 MHz_CDMA_upper






Uplink_1710 - 1755 MHz_GSM_lower




Uplink_1710 - 1755 MHz_GSM_upper






Uplink_1850 - 1910 MHz_GSM_lower




Uplink_1850 - 1910 MHz_GSM_upper






Uplink_704 - 716 MHz_GSM_lower




Uplink_704 - 716 MHz_GSM_upper






Uplink_776 - 787 MHz_GSM_lower




Uplink_776 - 787 MHz_GSM_upper






Uplink_824 - 849 MHz_GSM_lower




Uplink_824 - 849 MHz_GSM_upper






Uplink_1710 - 1755 MHz_WCDMA_lower




Uplink_1710 - 1755 MHz_WCDMA_upper






Uplink_1850 - 1910 MHz_WCDMA_lower




Uplink_1850 - 1910 MHz_WCDMA_upper






Uplink_704 - 716 MHz_WCDMA_lower




Uplink_704 - 716 MHz_WCDMA_upper






Uplink_776 - 787 MHz_WCDMA_lower




Uplink_776 - 787 MHz_WCDMA_upper






Uplink_824 - 849 MHz_WCDMA_lower




Uplink_824 - 849 MHz_WCDMA_upper






Downlink_734 - 746 MHz_CDMA_lower




Downlink_1930 - 1990 MHz_CDMA_lower





Downlink_1930 - 1990 MHz_CDMA_upper




Downlink_2110 - 2155 MHz_CDMA_lower






Downlink_734 - 746 MHz_CDMA_upper




Downlink_746 - 757 MHz_CDMA_lower






Downlink_746 - 757 MHz_CDMA_upper




Downlink_869 - 894 MHz_CDMA_lower






Downlink_869 - 894 MHz_CDMA_upper




Downlink_2110 - 2155 MHz_CDMA_upper






Downlink_1930 - 1990 MHz_GSM_lower




Downlink_1930 - 1990 MHz_GSM_upper






Downlink_2110 - 2155 MHz_GSM_lower




Downlink_734 - 746 MHz_GSM_lower






Downlink_734 - 746 MHz_GSM_upper




Downlink_746 - 757 MHz_GSM_lower






Downlink_746 - 757 MHz_GSM_upper




Downlink_869 - 894 MHz_GSM_lower






Downlink_869 - 894 MHz_GSM_upper




Downlink_2110 - 2155 MHz_GSM_upper






Downlink_1930 - 1990 MHz_WCDMA_lower




Downlink_1930 - 1990 MHz_WCDMA_upper






Downlink_2110 - 2155 MHz_WCDMA_lower




Downlink_2110 - 2155 MHz_WCDMA_upper






Downlink_734 - 746 MHz_WCDMA_lower




Downlink_734 - 746 MHz_WCDMA_upper






Downlink_746 - 757 MHz_WCDMA_lower




Downlink_746 - 757 MHz_WCDMA_upper





Downlink_869 - 894 MHz_WCDMA_lower



Downlink_869 - 894 MHz_WCDMA_upper

