


Annex H


Occupied Bandwidth



Uplink_CDMA Input_1710 - 1755 MHz




Uplink_CDMA Input_1850 - 1910 MHz






Uplink_CDMA Input_704 - 716 MHz




Uplink_CDMA Input_776 - 787 MHz







Uplink_CDMA Input_824 - 849 MHz




Uplink_CDMA Output_1710 - 1755 MHz



Uplink_CDMA Output_1850 - 1910 MHz




Uplink_CDMA Output_704 - 716 MHz






Uplink_CDMA Output_776 - 787 MHz




Uplink_CDMA Output_824 - 849 MHz






Uplink_GSM Input 1850 - 1910 MHz




Uplink_GSM Input_1710 - 1755 MHz






Uplink_GSM Input_704 - 716 MHz




Uplink_GSM Input_776 - 787 MHz







Uplink_GSM Input_824 - 849 MHz




Uplink_GSM Output 1850 - 1910 MHz



Uplink_GSM Output_1710 - 1755 MHz




Uplink_GSM Output_704 - 716 MHz






Uplink_GSM Output_776 - 787 MHz




Uplink_GSM Output_824 - 849 MHz






Uplink_WCDMA Input_1710 - 1755 MHz




Uplink_WCDMA Input_1850 - 1910 MHz






Uplink_WCDMA Input_704 - 716 MHz




Uplink_WCDMA Input_776 - 787 MHz






Uplink_WCDMA Input_824 - 849 MHz




Uplink_WCDMA Output_1710 - 1755 MHz






Uplink_WCDMA Output_1850 - 1910 MHz




Uplink_WCDMA Output_704 - 716 MHz






Uplink_WCDMA Output_776 - 787 MHz




Uplink_WCDMA Output_824 - 849 MHz






Downlink_CDMA Input_1930 - 1990 MHz




Downlink_CDMA Input_2110 - 2155 MHz






Downlink_CDMA Input_734 - 746 MHz




Downlink_CDMA Input_746 - 757 MHz






Downlink_CDMA Input_869 - 894 MHz




Downlink_CDMA Output_1930 - 1990 MHz






Downlink_CDMA Output_2110 - 2155 MHz




Downlink_CDMA Output_734 - 746 MHz






Downlink_CDMA Output_746 - 757 MHz




Downlink_CDMA Output_869 - 894 MHz






Downlink_GSM Input_1930 - 1990 MHz




Downlink_GSM Input_2110 - 2155 MHz






Downlink_GSM Input_734 - 746 MHz




Downlink_GSM Input_746 - 757 MHz






Downlink_GSM Input_869 - 894 MHz




Downlink_GSM Output_1930 - 1990 MHz






Downlink_GSM Output_2110 - 2155 MHz




Downlink_GSM Output_734 - 746 MHz






Downlink_GSM Output_746 - 757 MHz




Downlink_GSM Output_869 - 894 MHz






Downlink_WCDMA Input_1930 - 1990 MHz




Downlink_WCDMA Input_2110 - 2155 MHz






Downlink_WCDMA Input_734 - 746 MHz




Downlink_WCDMA Input_746 - 757 MHz






Downlink_WCDMA Input_869 - 894 MHz




Downlink_WCDMA Output_1930 - 1990 MHz






Downlink_WCDMA Output_2110 - 2155 MHz




Downlink_WCDMA Output_734 - 746 MHz





Downlink_WCDMA Output_746 - 757 MHz



Downlink_WCDMA Output_869 - 894 MHz

