

Boise, Idaho 83704
Phone: (208) 323-1000

www.PreViewRadar.com

Fax: (208) 323-1034



Dec 13, 2012

Subject: WorkSight PreView Sensor Model 428-7663-00

A new model of PreView radar sensor was created based on the previously FCC approved WorkZone PreView radar sensor (Model WZPV4015) and WorkSight PreView radar model WS6220 under FCC ID OXZWZPV2009. The following changes were made to the WorkSight WS6220 sensor to create the new WorkSight PreView sensor, model 428-7663-00:

Customer specific firmware for reporting detection indications.

No changes were made to the internal printed circuit assemblies (Antenna/RF or processor) to create this new WorkSight 428-7663-00 sensor.

This new model is electrically and mechanically identical to the models that were previously approved under FCC ID: OXZWZPV2009.

Regards,

Dale Hessing

Vice President of Engineering/Chief Technical Officer

Preco Electronics, Inc