

SerComm Corporation 中磊電子股份有限公司

 Taipei
 Office:
 8F, No.3-1, YuanQu St., NanKang, Taipei
 115, Taiwan, R.O.C.

 TEL:
 886-2-2655-3988
 FAX:
 886-2-2655-3966

 Chu Nan Office:
 3F, No. 81, YuYi Rd., Chu-Nan, Miao-Li
 350, Taiwan, R.O.C.

 TEL:
 886-37-585-899
 FAX:
 886-37-585-000

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: (P27IP1006AA)

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by SerComm Corporation will establish a new FCC ID under Belkin International, Inc. grantee code for purpose of marketing. The original grant to K7SF5D8231-4D. will remain in effect.

An authorization letter by Belkin International, Inc. is attached.

Per 2.933(b)

- 1. The original identification is K7SF5D8231-4D
- 2. The original grant date is 05/29/2007
- 3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.

The following files are electronically submitted as attachments:

Cover Letter External Photos FCC ID label format and location

Yours sincerely,

holp.

Ronnie Cheng



Associate Manager / R&D Division SerComm Corporation TEL: 886-2-2655-3988 #2547 FAX: 886-2-2655-3975 E-Mail: ronnie_cheng@sercomm.com