

22 July, 2015

Nemko Canada Inc  
303 River Road  
Ottawa, Ontario, Canada  
K1V 1H2

Attn: Director of Certification  
Re: FCC ID: P3YSPOTCELL0030

Part 20 Signal Booster Warning Label Attestation

Attestation per 935210 D02 Signal Booster Certification v03 with respect to paragraph d of section IV INDUSTRIAL (PART 20) SIGNAL BOOSTER SPECIFICS

Warning label messages will be also be shown in online and point-of-sale marketing materials and on outside packaging of device.

*Dated this* 22 *Day of* August *20 15*

*By:* JAY SENGUPTA

*Signature*

*Printed*

*Title:* Director, Engineering

*On behalf of:* Spotwave Wireless Ltd.

*Telephone:* 613-591-1662