

American TCB, Inc. 6731 Whittier Avenue Suite C110 McLean, VA 22101

Re: Mitac International Corporation
Portable Navigator
FCC ID: P4Q-2007VEN3001

FCC ID: P4Q-2007 VEN300

IC: 2420C-2007V301

Dear Sir or Madam:

Please be notified that we, the undersigned, Mitac International Corporation declare that the reasons for this Class 2 permissive change are as below:

- 1. Add a model name: Magellan [®] Maesttro TM 4010.
- 2. Update CPU from sansung2440 to Samsung2443.
- 3. Update the USB cable with a core.

Please refer to below form for details information:

Item	Key Components Deviation		Remark
	4050 & 4040	4010	
CPU	S3C2440A	S3C2443X	Samsung upgraed their product
Flash	K9K8G08U0M	K9LAG08U0M	change SLC chip to MLC
SDRAM	K4S561633F-XL	K4M51323PC-DG75	change 2chip to 1 chip
CPLD	LC4064ZC-75MN56C	XC2C64A-7CP56I	different source
LCD POWER IC	ADM8839	N/A	due to different Panel
LCD backlight control	MAX8595X	MAX1554	due to different Panel
LCD connector	FPC/FFC/51P/0.3MM	FPC/FFC/45P/0.3MM	due to different Panel
ECHO	VP1020	FM2010	product upgrated
USB/COM PORT SWITCH	NC7SB3157	TS3USB221	change 2chip to 1 chip
USB 1.2V POWER IC	N/A	AME8890	Due to the different CPU

If you have any question regarding this declaration, please do not hesitate to contact us.

Sincerely yours,

Joe Yang

Manager

Mitac International Corporation

2007/4/13