

Mr. Fujimoto:

In order for processing of this application (FCC ID: P4U-MNTB) to continue, the following issue(s) will have to be addressed:

- 1) The operational description submitted is insufficient. Please submit a new description describing what the device does, and its intended usage during normal operation, etc.
- 2) The users manual references a "frequency lock feature". Please explain this feature in detail.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website. Your correspondence number is P4U-MNTB-2.

Best regards,

Scott McCutchan  
Operations Manager  
Compatible Electronics TCB  
114 Olinda Drive  
Brea, CA 92823  
(714) 579-0500  
Fax (714) 579-1850