



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

January 22, 2007

RE: Eka Systems, Inc.

FCC ID: P9X2400B

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The FCC ID specified in the manual is not correct (pg 10). Additionally, the FCC on page 11 & 12 appears to show the FCC ID with a lower case "b". The FCC ID must consist of only upper case letters. Also, the FCC ID appears to be in several sections of the manual which appear to apply to other devices (page 17). Please review/correct.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.