


▼E91 1:1



Label position



There is no space to bear Part 15.19 statement due to the device is too small , the statement is specified in user manual.