



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

August 28, 2002

RE: TeLLUS Group Corp.

FCC ID: PB6-02011

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The updated DoC labeling is missing the 's' on Standards. The phrase should be "Tested to Comply With FCC Standards". Please update the label to include this.
- 2) The modular request letter references 13 pages of data sheets for the "ISL3873B". This was not provided. Please provide this.
- 3) For the users manual to be in compliance with 2.1077, the following information must be on the same page as the FCC Statements:
 - (a) Identification of the product, i.e. name and model number.
 - (b) The identification, by name, address and telephone number, of the responsible party. The responsible party is defined as either the manufacturer, or if the equipment is imported, the importer. The responsible party for a Declaration of Conformity must be located within the United States.
- 4) Item 7 in the modular letter references specific information that does not appear to be in the users manual. However, for this approval we would recommend more information be added to the manual for completeness. Additionally, the users manual references installing the card in a computer, but this device is only supposed to be for integrators (as given in our previous discussions) where certain conditions can be maintained. Please correct the manual to include the information given in the additional attachment.
- 5) The new bandedge plots provided (RBW/VBW unknown) to show compliance with the 54 dBuV/m appear about 8 dB below the plots given in the original report in section 7.5 (RBW = 100 kHz, VBW = 100 kHz). Please explain:
 - (a) why there is this difference
 - (b) provide the RBW & VBW of the new measurements
 - (c) explain if this measurement was radiated or conducted. It should have been radiated.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.