


Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs



Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs




Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs




Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	B

Test Configuration Photograph #1



Client: Intel Mobile Communications	Job Number: J94122
Model: 3160SDW	T-Log Number: T94177
	Project Manager: Christine Krebill
Contact: Steve Hackett	Project Coordinator: -
Standard: FCC Part 15, RSS-210	Class: B

Test Configuration Photograph #1
(Conducted Emissions - Power Port)



Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	B

Test Configuration Photograph #2
(Conducted Emissions - Power Port)

