



Date: 4.JUL.2022 18:09:08

BE-NR-LOW, MIMO-A, 802.11n20-HT8, Ch177




Date: 4.JUL.2022 18:09:22

BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch177




Date: 4.JUL.2022 18:11:05

BE-NR-LOW, MIMO-A, 802.11n40-HT8, Ch175




Date: 4.JUL.2022 18:21:24

BE-NR-HIGH, MIMO-A, 802.11n40-HT8, Ch175




Date: 4.JUL.2022 18:12:16

BE-NR-LOW, MIMO-A, 802.11ac80-VHT0, Ch171




Date: 4.JUL.2022 18:22:31

BE-NR-HIGH, MIMO-A, 802.11ac80-VHT0, Ch171




Date: 4.JUL.2022 18:14:58

BE-NR-LOW, MIMO-A, 802.11ax20-HE0, Ch177




Date: 4.JUL.2022 18:15:11

BE-NR-HIGH, MIMO-A, 802.11ax20-HE0, Ch177




Date: 4.JUL.2022 18:16:54

BE-NR-LOW, MIMO-A, 802.11ax40-HE0, Ch175




Date: 4.JUL.2022 18:24:22

BE-NR-HIGH, MIMO-A, 802.11ax40-HE0, Ch175




Date: 29.JUL.2022 17:20:04

BE-NR-LOW, MIMO-A, 802.11ax80-HE0, Ch171




Date: 4.JUL.2022 18:25:46

BE-NR-HIGH, MIMO-A, 802.11ax80-HE0, Ch171




Date: 5.JUL.2022 11:25:19

BE-NR-LOW, MIMO-B, 802.11n20-HT8, Ch177




Date: 5.JUL.2022 11:25:33

BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch177




Date: 5.JUL.2022 15:39:54

BE-NR-LOW, MIMO-B, 802.11n40-HT8, Ch175




Date: 5.JUL.2022 15:40:07

BE-NR-HIGH, MIMO-B, 802.11n40-HT8, Ch175




Date: 5.JUL.2022 11:28:28

BE-NR-LOW, MIMO-B, 802.11ac80-VHT0, Ch171




Date: 5.JUL.2022 11:28:42

BE-NR-HIGH, MIMO-B, 802.11ac80-VHT0, Ch171




Date: 5.JUL.2022 11:31:11

BE-NR-LOW, MIMO-B, 802.11ax20-HE0, Ch177




Date: 5.JUL.2022 11:31:24

BE-NR-HIGH, MIMO-B, 802.11ax20-HE0, Ch177




Date: 5.JUL.2022 11:33:08

BE-NR-LOW, MIMO-B, 802.11ax40-HE0, Ch175




Date: 5.JUL.2022 11:33:22

BE-NR-HIGH, MIMO-B, 802.11ax40-HE0, Ch175



Date: 5.JUL.2022 11:50:04


BE-NR-LOW, MIMO-B, 802.11ax80-HE0, Ch171



Date: 5.JUL.2022 11:39:26


BE-NR-HIGH, MIMO-B, 802.11ax80-HE0, Ch171

B.3.6 Undesirable emission limits : out of band Peak (Conducted)




Date: 25.AUG.2022 11:13:50

BE-NR-HIGH, SISO-A, 802.11a20-6Mbps, Ch177




Date: 25.AUG.2022 11:17:12

BE-NR-HIGH, SISO-A, 802.11n20-HT0, Ch177




Date: 25.AUG.2022 11:17:43

BE-NR-HIGH, SISO-A, 802.11n40-HT0, Ch175




Date: 25.AUG.2022 11:18:15

BE-NR-HIGH, SISO-A, 802.11ac80-VHT0, Ch171



Date: 25.AUG.2022 11:18:47


BE-NR-HIGH, SISO-A, 802.11ax20-HE0, Ch177



Date: 25.AUG.2022 11:19:18


BE-NR-HIGH, SISO-A, 802.11ax40-HE0, Ch175

Test Report N° 210209-01.TR46




Date: 25.AUG.2022 11:19:50

BE-NR-HIGH, SISO-A, 802.11ax80-HE0, Ch171




Date: 24 AUG 2022 18:28:05

BE-NR-HIGH, SISO-B, 802.11a20-6Mbps, Ch177




Date: 24 AUG 2022 18:38:29

BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch177




Date: 24 AUG 2022 18:39:01

BE-NR-HIGH, SISO-B, 802.11n40-HT0, Ch175




Date: 24 AUG 2022 18:39:33

BE-NR-HIGH, SISO-B, 802.11ac80-VHT0, Ch171



Date: 24 AUG 2022 18:40:04


BE-NR-HIGH, SISO-B, 802.11ax20-HE0, Ch177



Date: 24 AUG 2022 18:40:36


BE-NR-HIGH, SISO-B, 802.11ax40-HE0, Ch175

Test Report N° 210209-01.TR46




Date: 24.AUG.2022 18:41:07

BE-NR-HIGH, SISO-B, 802.11ax80-HE0, Ch171




Date: 25.AUG.2022 11:40:47

BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch177




Date: 25.AUG.2022 11:43:42

BE-NR-HIGH, MIMO-A, 802.11n40-HT8, Ch175




Date: 25.AUG.2022 11:44:14

BE-NR-HIGH, MIMO-A, 802.11ac80-VHT0, Ch171



Date: 25.AUG.2022 11:44:46


BE-NR-HIGH, MIMO-A, 802.11ax20-HE0, Ch177



Date: 25.AUG.2022 11:45:18

BE-NR-HIGH, MIMO-A, 802.11ax40-HE0, Ch175


Test Report N° 210209-01.TR46



Date: 25.AUG.2022 11:45:50


BE-NR-HIGH, MIMO-A, 802.11ax80-HE0, Ch171

Test Report N° 210209-01.TR46




Date: 25.AUG.2022 10:48:22

BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch177




Date: 25.AUG.2022 10:51:59

BE-NR-HIGH, MIMO-B, 802.11n40-HT8, Ch175




Date: 25.AUG.2022 10:52:31

BE-NR-HIGH, MIMO-B, 802.11ac80-VHT0, Ch171



Date: 25.AUG.2022 10:53:02


BE-NR-HIGH, MIMO-B, 802.11ax20-HE0, Ch177



Date: 25.AUG.2022 10:53:34

BE-NR-HIGH, MIMO-B, 802.11ax40-HE0, Ch175

Test Report N° 210209-01.TR46



Date: 25.AUG.2022 10:54:07

BE-NR-HIGH, MIMO-B, 802.11ax80-HE0, Ch171