



B.3.4 Undesirable emission limits : out of band (Conducted)




Date: 15/MAR/2022 09:19:04

BE-R-LOW, SISO-A, 802.11a20-6Mbps, Ch100




Date: 15/MAR/2022 09:19:16

BE-NR-LOW, SISO-A, 802.11a20-6Mbps, Ch100




Date: 15/MAR/2022 09:21:11

BE-NR-HIGH, SISO-A, 802.11a20-6Mbps, Ch140




Date: 15/MAR/2022 09:24:53

BE-R-LOW, SISO-A, 802.11n20-HT0, Ch100




Date: 15/MAR/2022 09:25:05

BE-NR-LOW, SISO-A, 802.11n20-HT0, Ch100




Date: 15/MAR/2022 09:27:00


BE-NR-HIGH, SISO-A, 802.11n20-HT0, Ch140




BE-R-LOW, SISO-A, 802.11n40-HT0, Ch102




BE-NR-LOW, SISO-A, 802.11n40-HT0, Ch102




BE-NR-HIGH, SISO-A, 802.11n40-HT0, Ch134




BE-R-LOW, SISO-A, 802.11ac80-VHT0, Ch106



BE-NR-LOW, SISO-A, 802.11ac80-VHT0, Ch106




BE-NR-HIGH, SISO-A, 802.11ac80-VHT0, Ch122




Date: 15 MAR 2022 10:10:16

BE-R-LOW, SISO-A, 802.11ac160-VHT0, Ch114




Date: 15 MAR 2022 10:10:29

BE-NR-LOW, SISO-A, 802.11ac160-VHT0, Ch114




Date: 15 MAR 2022 10:10:43

BE-NR-HIGH, SISO-A, 802.11ac160-VHT0, Ch114




Date: 15 MAR 2022 09:35:28

BE-R-LOW, SISO-A, 802.11ax20-HE0, Ch100




Date: 15 MAR 2022 09:35:41

BE-NR-LOW, SISO-A, 802.11ax20-HE0, Ch100




Date: 15 MAR 2022 09:40:48

BE-NR-HIGH, SISO-A, 802.11ax20-HE0, Ch140




Date: 15 MAR 2022 09:50:17

BE-R-LOW, SISO-A, 802.11ax40-HE0, Ch102




Date: 15 MAR 2022 09:50:29

BE-NR-LOW, SISO-A, 802.11ax40-HE0, Ch102




Date: 15 MAR 2022 09:53:36

BE-NR-HIGH, SISO-A, 802.11ax40-HE0, Ch134




Date: 15 MAR 2022 09:58:18

BE-R-LOW, SISO-A, 802.11ax80-HE0, Ch106



Date: 15 MAR 2022 09:58:30


BE-NR-LOW, SISO-A, 802.11ax80-HE0, Ch106



Date: 15 MAR 2022 10:00:22


BE-NR-HIGH, SISO-A, 802.11ax80-HE0, Ch122

Test Report N° 220225-03.TR02




Date: 15.MAR.2022 10:03:37

BE-R-LOW, SISO-A, 802.11ax160-HE0, Ch114




Date: 15.MAR.2022 10:03:49

BE-NR-LOW, SISO-A, 802.11ax160-HE0, Ch114




Date: 15.MAR.2022 10:04:03

BE-NR-HIGH, SISO-A, 802.11ax160-HE0, Ch114




Date: 17.MAR.2022 17:12:32

BE-R-LOW, SISO-B, 802.11a20-6Mbps, Ch100




Date: 17.MAR.2022 17:12:45

BE-NR-LOW, SISO-B, 802.11a20-6Mbps, Ch100




Date: 17.MAR.2022 17:14:37

BE-NR-HIGH, SISO-B, 802.11a20-6Mbps, Ch140




Date: 17.MAR.2022 17:18:12

BE-R-LOW, SISO-B, 802.11n20-HT0, Ch100




Date: 17.MAR.2022 17:19:19

BE-NR-LOW, SISO-B, 802.11n20-HT0, Ch100




Date: 17.MAR.2022 17:44:14

BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch140




Date: 17.MAR.2022 17:47:58

BE-R-LOW, SISO-B, 802.11n40-HT0, Ch102




Date: 17.MAR.2022 17:48:10

BE-NR-LOW, SISO-B, 802.11n40-HT0, Ch102




Date: 17.MAR.2022 17:50:07

BE-NR-HIGH, SISO-B, 802.11n40-HT0, Ch134




Date: 17.MAR.2022 18:21:39

BE-R-LOW, SISO-B, 802.11ac80-VHT0, Ch106




Date: 17.MAR.2022 18:21:51

BE-NR-LOW, SISO-B, 802.11ac80-VHT0, Ch106




Date: 17.MAR.2022 18:22:35


BE-NR-HIGH, SISO-B, 802.11ac80-VHT0, Ch122




BE-R-LOW, SISO-B, 802.11ac160-VHT0, Ch114




BE-NR-LOW, SISO-B, 802.11ac160-VHT0, Ch114




BE-NR-HIGH, SISO-B, 802.11ac160-VHT0, Ch114




BE-R-LOW, SISO-B, 802.11ax20-HE0, Ch100



BE-NR-LOW, SISO-B, 802.11ax20-HE0, Ch100




BE-NR-HIGH, SISO-B, 802.11ax20-HE0, Ch140




Date: 17.MAR.2022 18:03:09

BE-R-LOW, SISO-B, 802.11ax40-HE0, Ch102




Date: 17.MAR.2022 18:03:22

BE-NR-LOW, SISO-B, 802.11ax40-HE0, Ch102




Date: 17.MAR.2022 18:03:10

BE-NR-HIGH, SISO-B, 802.11ax40-HE0, Ch134




Date: 17.MAR.2022 18:13:22

BE-R-LOW, SISO-B, 802.11ax80-HE0, Ch106



Date: 17.MAR.2022 18:13:34


BE-NR-LOW, SISO-B, 802.11ax80-HE0, Ch106




Date: 17.MAR.2022 18:15:13

BE-NR-HIGH, SISO-B, 802.11ax80-HE0, Ch122


Test Report N° 220225-03.TR02




Date: 17.MAR.2022 18:18:09
BE-R-LOW, SISO-B, 802.11ax160-HE0, Ch114



Date: 17.MAR.2022 18:18:21
BE-NR-LOW, SISO-B, 802.11ax160-HE0, Ch114




Date: 17.MAR.2022 18:18:35
BE-NR-HIGH, SISO-B, 802.11ax160-HE0, Ch114




Date: 15 MAR 2022 11:47:15

BE-R-LOW, MIMO-A, 802.11n20-HT8, Ch100




Date: 15 MAR 2022 11:47:27

BE-NR-LOW, MIMO-A, 802.11n20-HT8, Ch100




Date: 15 MAR 2022 11:49:26

BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch140




Date: 16 MAR 2022 11:57:15

BE-R-LOW, MIMO-A, 802.11n40-HT8, Ch102




Date: 16 MAR 2022 11:57:27

BE-NR-LOW, MIMO-A, 802.11n40-HT8, Ch102




Date: 15 MAR 2022 11:55:29

BE-NR-HIGH, MIMO-A, 802.11n40-HT8, Ch134




Date: 16/MAR/2022 14:28:53

BE-R-LOW, MIMO-A, 802.11ac80-VHT0, Ch106




Date: 16/MAR/2022 12:10:49

BE-NR-LOW, MIMO-A, 802.11ac80-VHT0, Ch106




Date: 16/MAR/2022 14:31:21

BE-NR-HIGH, MIMO-A, 802.11ac80-VHT0, Ch122




Date: 15/MAR/2022 12:31:50

BE-R-LOW, MIMO-A, 802.11ac160-VHT0, Ch114




Date: 15/MAR/2022 12:32:03

BE-NR-LOW, MIMO-A, 802.11ac160-VHT0, Ch114




Date: 15/MAR/2022 12:32:17

BE-NR-HIGH, MIMO-A, 802.11ac160-VHT0, Ch114




Date: 15MAR2022 11:58:07

BE-R-LOW, MIMO-A, 802.11ax20-HE0, Ch100




Date: 15MAR2022 11:58:19

BE-NR-LOW, MIMO-A, 802.11ax20-HE0, Ch100




Date: 15MAR2022 12:03:11

BE-NR-HIGH, MIMO-A, 802.11ax20-HE0, Ch140




Date: 16MAR2022 12:01:41

BE-R-LOW, MIMO-A, 802.11ax40-HE0, Ch102



Date: 15MAR2022 12:12:31


BE-NR-LOW, MIMO-A, 802.11ax40-HE0, Ch102



Date: 15MAR2022 12:15:33


BE-NR-HIGH, MIMO-A, 802.11ax40-HE0, Ch134

Test Report N° 220225-03.TR02




Date: 16MAR2022 14:24:42

BE-R-LOW, MIMO-A, 802.11ax80-HE0, Ch106




Date: 16MAR2022 12:07:32

BE-NR-LOW, MIMO-A, 802.11ax80-HE0, Ch106




Date: 15MAR2022 12:22:08

BE-NR-HIGH, MIMO-A, 802.11ax80-HE0, Ch122




Date: 15MAR2022 12:25:12

BE-R-LOW, MIMO-A, 802.11ax160-HE0, Ch114




Date: 15MAR2022 12:25:25

BE-NR-LOW, MIMO-A, 802.11ax160-HE0, Ch114




Date: 15MAR2022 12:25:30

BE-NR-HIGH, MIMO-A, 802.11ax160-HE0, Ch114




Date: 17.MAR.2022 19:57:42

BE-R-LOW, MIMO-B, 802.11n20-HT8, Ch100




Date: 17.MAR.2022 19:57:54

BE-NR-LOW, MIMO-B, 802.11n20-HT8, Ch100




Date: 17.MAR.2022 19:59:47

BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch140




Date: 18.MAR.2022 15:17:28

BE-R-LOW, MIMO-B, 802.11n40-HT8, Ch102




Date: 17.MAR.2022 20:03:35

BE-NR-LOW, MIMO-B, 802.11n40-HT8, Ch102




Date: 17.MAR.2022 20:05:27


BE-NR-HIGH, MIMO-B, 802.11n40-HT8, Ch134




Date: 17.MAR.2022 20:45:41
BE-R-LOW, MIMO-B, 802.11ac80-VHT0, Ch106




Date: 17.MAR.2022 20:45:53
BE-NR-LOW, MIMO-B, 802.11ac80-VHT0, Ch106




Date: 17.MAR.2022 20:43:41
BE-NR-HIGH, MIMO-B, 802.11ac80-VHT0, Ch122



Date: 17.MAR.2022 20:43:38
BE-R-LOW, MIMO-B, 802.11ac160-VHT0, Ch114



Date: 17.MAR.2022 20:42:50
BE-NR-LOW, MIMO-B, 802.11ac160-VHT0, Ch114



Date: 17.MAR.2022 20:43:04
BE-NR-HIGH, MIMO-B, 802.11ac160-VHT0, Ch114