



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 14, 2004

RE: FCC ID: PD9WM3A2915ABG_ATCB001471

Attention: Rick Candelas

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

FCC

1. Please note that the tune up procedure and other documentation indicates that this device operates on non-US frequencies. Please provide information explaining how non-US frequencies are prevented from being accessed by the user and how these non-US frequencies are disabled so the OEM integrator cannot enable them. If this information has been provided, please give the location of this information.
2. In the note on page 119 of the manual it states, "To avoid the possibility of exceeding the FCC radio frequency exposure limits, you should keep a distance of at least 2 cm between you (or any other person in the vicinity) and the antenna that is built into the computer." As this can only be in stalled with a mandatory 20cm separation requirement, shouldn't this statement also indicate 20cm? Please verify and correct as necessary.
3. Please note that there does not appear to be OEM instructions to place a label on the host as follows or similar, "Contains FCC ID: PD9WM3A2915ABG". Please explain.

Industry Canada

4. Please note that in the FCB process the company numbers of both the applicant and the Existing Canadian representative need to be provided. Please provide the IC company number for the Existing Canadian representative for this application. If this is not known, or if this is not an existing contact, please advise if this is to be listed as a New Contact. If this is an existing contact and you do not know the IC company number you may email certification.bureau@ic.gc.ca with the name address and contact person name for this information.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.