



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

June 20, 2006

RE: FCC ID: PDNRM-170_ATCB003594
Attention: Timo Seppala

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the EMC report apparently is for the RM170. The SAR report is for both the RM170 and the RM171. Please note that the FCC and IC documentation appears to be for only the RM170. Please explain the SAR data for the RM171 in this filing. Please remove data that is not pertinent to this filing.
2. Please note that while it may be OK to list the SAR values for both models in a similar manual, the SAR values for this specific application (RM-170) must be addressed. The SAR values in the manual only address the RM171 model. Please provide a manual that addresses the specifics of this application.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.