

Re: Class II Permissive Change/Re-assessment
for Bosch BSM RKE Receiver
P/Ns: 6002JE0019, 6002JE0016, 6002JE0015
FCC ID: PFJSIP1V6
CANADA: to be provided by IC

FCC/IC ID LABEL & LOCATION

Since there are no changes to the FCC/IC Label or its Location, and the associated documentation was originally submitted, such is not repeated here.