

310 Providence Mine Road Nevada City, CA 95959 USA

Phone 530.274.5472 Fax 530.273.6340 2Wire, Inc. 1704 Automation Parkway San Jose, CA 95131

> Tel 408.428.9500 Fax 408.428.9590 www.2Wire.com

November 17, 2010

## Declaration of Similarity (DoS) for Product Families

To Whom it May Concern:

We, the undersigned manufacturer, 2Wire, Inc, confirm hereby that the following models are identical in all electrical safety, telecom and electromagnetic aspects from a regulatory perspective. The system tested was the 4112N ADSL Wireless Residential Gateway and represents a typical worst-case installation. The following table describes the model number differences.

## **Model Differences:**

4111N:

Ethernet WAN: 1 port (10/100) Ethernet LAN: 4 port (10/100)

4112N:

Ethernet WAN: 1 port (10/100/1000)

Ethernet LAN: 1 port (GigE) - 3 ports (10/100)

Sincerely,

Mark Rieger

Staff Regulatory Compliance Engineer 2Wire, Inc. DBA Pace Americas

310 Providence Mine Road, Ste. 200 Nevada City, CA 95959 USA

530.274.5440 direct 530.575.6010 mobile 530.273.6340 fax

mark.rieger@pace.com