



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 18, 2001

RE: Alinco, Inc.

FCC ID: PH3DJ-S40T

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide a clearer or higher resolution copy of the schematics. Portions of the schematic are not readable. [Uploaded schematics](#)
- 2) The attachments provided for external photographs and the labeling information show conflicting warning labeling information (i.e., one shows labeling information for 15.19(a)(1), while the other states the labeling specified by 15.19(a)(3)). Please clarify this issue and also explain why the unit has been labeled for DoC. [The revised label information will be what Alinco will place on the device.](#) [New External photos also uploaded](#)
- 3) Section 3.1 of the test report states that the EUT was locked to a set frequency, yet the next sentence states that the scanning mode was deemed the worst case mode. Please clarify this issue. [Revised Section 3.1 of the test report. Please refer to 11-20-01 test report](#)
- 4) The test equipment listed in section 5.1 of the report does not match the test equipment specified in Table 12 of the test report. The correction factors appear to include preamplifier gain, yet Table 12 does not specify a preamplifier. Please clarify these discrepancies. [Revised Section 5.1 of test report and Table 12. Please refer to 11-20-01 test report](#)

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.