



Company name: Airspan Networks Inc.  
Address: 777 Yamato Rd, Suite 310  
Boca Raton, Florida 33431  
USA

### **ProST 2.5 GHz Tune up procedure**

Each ProST radio has been tested by automatic test station. As part of the test , the maximum RF output power value has been masured. In case the RF output power is higher then specified in the System Description, the ProST radio doesn't pass the test and get Fail status.

The ProST boards with Fail status cannot be assembled as part of final product.

Name of authorized person: Zion Levy  
Position: Compliances & Testing Engineer

A handwritten signature in black ink, appearing to read "Zion Levy", written over a horizontal line.

Date: June 17, 2009

Airspan Networks (Israel) Ltd., Israel  
Tel: +972-3-9777444 ; Fax: +972-3-9777400, [www.airspan.com](http://www.airspan.com)