



FCC ID:PIDMMAX36

Company name: Airspan Networks (Israel) Ltd
Address: Harava St, "Unitronics" building
Airport City 70100, P.O.199
Israel

MicroMAX 3.7GHz Tune up procedure

Each MicroMAX radio has been tested by automatic test station. As part of the test, the Maximum RF output power value has been measured. In case the RF output power is higher than specified in the System Description, the MicroMAX radio doesn't pass the test and get Fail status. MicroMAX boards with Fail status can not be assembled as part of final product.

Name of authorized person: Zion Levy
Position: Compliances & Testing Engineer

A handwritten signature in black ink, appearing to be "Zion Levy", written over a light blue horizontal line.

Date: May 21, 2008

Airspan Networks (Israel) Ltd., Israel
Tel: +972-3-9777444 ; Fax: +972-3-9777400, www.airspan.com