

Company name: Address: Airspan Networks Inc. 777 Yamato Road Suite 310 Boca Raton FL 33431 USA

FCC ID:PIDMMAX3605

## MacroMAXe 3605 3.7G Ext Tune up procedure

Each MacroMAXe radio has been tested by automatic test station. As part of the test, the maximum RF output power value has been masured. In case the RF output power is higher then specified in the System Description, the MacroMAXe radio doesn't pass the test and get Fail status. The MacroMAXe boards with Fail status can not be assembled as part of the final product.

Name of authorized person: Position: Zion Levy Compliances & Testing Engineer

Date: January 31, 2010

Airspan Networks Inc. Tel: +1 561 893-8670; Fax: +1 561 893-8671, www.airspan.com