

FCC ID:PIDMMAX37

Company name: Airspan Networks (Israel) Ltd Address: Harava St,"Unitronics" building Airport City 70100, P.O.199 Israel

MicroMAX 3.7GHz Tune up procedure

Each MicroMAX radio has been tested by automatic test station. As part of the test, the Maximum RF output power value has been masured. In case the RF output power is higher then specified in the System Description, the MicroMAX radio doesn't pass the test and get Fail status. MicroMAX boards with Fail status can not be assembled as part of final product.

Name of authorized person: Position: Zion Levy Compliances & Testing Engineer

Date: December 31, 2007

Airspan Networks (Israel) Ltd., Israel Tel: +972-3-9777444 ; Fax: +972-3-9777400, www.airspan.com