

INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W

INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21


(Internal)



Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W


INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W

INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W


INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W

INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W


INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W

INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



FCC ID: PIYDPX21-16A5W
IC: 4390C-DPX2116A5W


INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16080221HKG-001

Equipment Photographs

Model : DPX21

(Internal)

