



**Mattel Asia Pacific Sourcing Limited**

**美泰玩具亞太有限公司**

---

## Request for Class II Permissive Change

FCC ID : PIYFBL83-16A5T

Date : 14-Apr-2017

TO : Federal Communication Commission

Please be notified that we, the undersigned, Mattel Asia Pacific Sourcing Limited declare that the reasons for this Class II permissive change are as below :

(Describe the difference between the product in original ID and current one. 详细描述新产品和原来产品的差异。)

Original ID model: FBL83

Current models: FDY09, FGT82 and FGT83

Difference in controller: Audio change and add a resistor (R6) to fix the circuit bug in FBL83.

Thank you.

Sincerely.

By: 申请商在 FCC 网站的联系人签名

\_\_\_\_\_  
Joule Mak

\_\_\_\_\_  
(Signature<sup>1</sup>)

\_\_\_\_\_  
(Print name)

Title: \_\_\_\_\_ Director Electronic Engineering\_\_\_\_\_

On behalf of: \_\_\_\_\_ Mattel Asia Pacific Sourcing Limited \_\_\_\_\_  
(Company Name)

Telephone: \_\_\_\_\_ +852 31855208 \_\_\_\_\_