

The Linksys Group, Inc.
17401 Armstrong Ave., Irvine,
CA 92614, U.S.A.

Description of Permissive Change

This report is prepared for FCC Class II permissive change. The differences compared with the original one are:

1. Remove the Home PNA jack and component.

Signatory,

A handwritten signature in black ink, appearing to be 'Lynk', written in a cursive style.