



DATE 4/27/2008

The following changes has been made on Navini Networks 2.5-2.6 PMX card (FCC ID: PL6-2500-PCM-R3:

- (1) FPGA swapped out for a bigger size;
- (2) Flash Swapped out for a bigger one (no PCB change);
- (3) Adding copper tape on the Digital board.

Best regards,

Larry Zhou

Regulatory Engineer.

Navini Networks 2240 Campbell Creek Blvd. Suite 110 Richardson TX 75082 972-852-4267