


#### **INTERNAL VIEW-1 OF EUT-1**

Report No.: HK1811091545E

INTERNAL VIEW-2 OF EUT-1







Page 50 of 60



## INTERNAL VIEW-3 OF EUT-1



INTERNAL VIEW-4 OF EUT-1







#### Report No.: HK1811091545E

## **OPEN VIEW-3 OF EUT-2**




## **INTERNAL VIEW-1 OF EUT-2**









## INTERNAL VIEW-2 OF EUT-2




# INTERNAL VIEW-3 OF EUT-2










## INTERNAL VIEW-4 OF EUT-2

INTERNAL VIEW-5 OF EUT-2





Page 55 of 60

#### Report No.: HK1811091545E

Part 2 TOP VIEW OF EUT



## BOTTOM VIEW OF EUT





## FRONT VIEW OF EUT




# BACK VIEW OF EUT





## Report No.: HK1811091545E





**RIGHT VIEW OF EUT** 



#### Report No.: HK1811091545E



#### **OPEN VIEW-1 OF EUT**




**OPEN VIEW-2 OF EUT** 







## **OPEN VIEW-3 OF EUT**



INTERNAL VIEW-1 OF EUT







INTERNAL VIEW-2 OF EUT

----END OF REPORT----