



SOMA Networks, Inc.

185 Berry Street, Suite 4600 • San Francisco, California 94107

July 20, 2006

ATTN:Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

RE: MPE Testing not required for NPM, Model # NPM-2500-C410, FCC ID:
POZNPM700007168A

To Whom It May Concern:

The antenna(s) used for this transmitter must be fixed/mounted on outdoor permanent structures. RF exposure compliance is addressed at the time of licensing, as required by the responsible FCC Bureau(s), including antenna co-location requirements of §1.1307(b)(3).

Sincerely,

A handwritten signature in black ink, appearing to read "Robin Grindley".

Robin Grindley
Chief Scientist – Hardware Systems
SOMA Networks, Inc.