


Change of Contents for FCC ID: PP4EZ2

1) PAM vendor changed.

We have changed PAM vendor from Anadigics to Avago, because Anadigics has a shortage problem.

- Part No.(Anadigics) : AWT6307R(Cellular),
AWT6308R(PCS)
- Part No. (Avago) : WS1103-Tr1(Cellular),
WS1403-Tr1(PCS)



Avago PAMs need external voltage regulation components and appropriate matching values.

(Transistor: KRX104E).

- Part No. (KEC in South Korea) : KRX104E

2) PCB minor Changed.(TX part)

According to the PAM change, PCB was also minor changed.