

April 18, 2002

Federal Communications Commission
Equipment Approval Services
7435 Oakland Mills Road
Columbia, MD 21046
Attn: Mr. Martin Perrin

SUBJECT: Hyundai Curitel Inc.
FCC ID: PP4HWP-230
731 Confirmation No.: EA497441
Correspondence Reference No.: 22160
Request for Tech. Info.: 3/4/2002

Dear Martin:

Transmitted herewith, on behalf of Hyundai Curitel Inc., is an amendment provided in response to the request for technical information dated March 4, 2002.


EMC

1. We confirmed with Hyundai that no external battery is available for this unit. Should one become available a permissive change will be filed if applicable.
2. The optional external antenna for this device is not available at this time, when one becomes available a class II Permissive Change will be applied.
3. The tuned channels at the band edges are channel 25 (1851.25 MHz) and channel 1175 (1908.75MHz).

SAR

1. Please find the attached page of the user's manual containing the RF warning statement for both internal and optional external antenna system.
2. The phone was controlled using software codes and the power was checked before and after each SAR test.
3. Please find the attached probe calibration certificate.
4. Please find the attached validation plot for the PCS band.
5. Please find attached the SAR test plots
6. Please find attached the revised uncertainty calculation.

We trust this information is sufficient to issue the grant as soon as possible. If you have any further questions, please do not hesitate to contact us.



Randy Ortanez
President

cc: Hyundai Curitel Inc.