

## Appendix D. Product Photos

DUT: WLAN Module (Brand Name: Atheros / Model Name: AR5BHB92)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PPD-AR5BHB92 Page Number : D1 of D3
Report Issued Date : Mar. 02, 2010
Report Version : Rev. 01

Report No. : FA021101-01





Report No. : FA021101-01

**Host: Convertible Tablet Computer** 

Model Name: NL2\*\* (The"\*"can be 0-9, A-Z or blank for the marketing purpose)




DUT with Thin Battery (4400 mAh)


**DUT with Thick Battery (7650 mAh)** 


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PPD-AR5BHB92 Page Number : D2 of D3
Report Issued Date : Mar. 02, 2010
Report Version : Rev. 01









**Battery 3\_Front View** 

Battery 3\_Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PPD-AR5BHB92 Page Number : D3 of D3
Report Issued Date : Mar. 02, 2010
Report Version : Rev. 01

Report No. : FA021101-01



Report No. : FA021101-01

## Appendix E. Test Setup Photos




Fig 9.1 Bottom of Laptop Touching with 0 cm AirFig 9.2 Bottom of Laptop Touching with 0 cm Air Gap (DUT with Battery 1)

Gap (DUT with Battery 2)



Fig 9.3 Bottom of Laptop Touching with 0 cm Air Gap (DUT with Battery 3)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PPD-AR5BHB92 Page Number : E1 of E1
Report Issued Date : Mar. 02, 2010
Report Version : Rev. 01




Fig 9.4 Bottom of Tablet Touching with 0 cm Air Fig 9.5 Bottom of Tablet Touching with 0 cm Air

Gap (DUT with Battery 1)

Gap (DUT with Battery 2)



Fig 9.6 Bottom of Tablet Touching with 0 cm Air

Gap (DUT with Battery 3)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PPD-AR5BHB92 Page Number : E2 of E3
Report Issued Date : Mar. 02, 2010
Report Version : Rev. 01

Report No. : FA021101-01



Fig 9.7 Primary Landscape

Fig 9.8 Secondary Landscape

Report No.: FA021101-01



Fig 9.9 Primary Portrait

**Note:** The test position of Secondary Portrait wasn't performed because the distance between WLAN antenna and this edge was larger than 5 cm. We expect that the SAR value for this position will very low.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PPD-AR5BHB92 Page Number : E3 of E3
Report Issued Date : Mar. 02, 2010

Report Version : Rev. 01