
10. SETUP PHOTOS


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




DATE: JULY 10, 2013

IC: 4104A-QCA6234


RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION












FAX: (510) 661-0888







POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP EUT AC/DC adapter connected to LISN:





Laptop connected to LISN:





END OF REPORT

Page 63 of 63