

10. SETUP PHOTOS

POWER MEASUREMENT SETUP





Page 53 of 57



Page 54 of 57

RADIATED RF MEASUREMENT SETUP






UL VERIFICATION SERVICES INC 47173 BENICIA STREET, FREMONT, CA 94538, USA This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc. FORM NO: CCSUP4701I FAX: (510) 661-0888 TEL: (510) 771-1000 FAX: (510) 661-0888 TEL: (510) 771-1000 FAX: (510) 661-0888 FORM NO: CCSUP4701I

Page 55 of 57


FREQUENCY STABILITY SETUP



Page 56 of 57

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT

Page 57 of 57