

MODEL NO. SD4-MC(US) PHOTO-ELECTRONIC DETECTION PRINCIPLE
FCC ID: PPJSD4418SC 418MHz WIRELESS SINGLE STATION SMOKE ALARM
FACTORY SENS. 1.0%- 4.0% PER FT. OBSCURATION 85DB SOUNDER

WARNING: USE ONLY BATTERIES SPECIFIED IN MARKING. USE OF A DIFFERENT BATTERY WILL HAVE A DETRIMENTAL EFFECT ON THE SMOKE ALARM OPERATION. **REPLACEMENT BATTERY USE PANASONIC CR123A / DURACELL DL123A ONLY.** CONSTANT EXPOSURES TO HIGH OR LOW TEMPERATURES OR HIGH HUMIDITY MAY REDUCE BATTERY LIFE. REFER TO INSTALL GUIDE 108137 FOR INSTALLATION, MAINTENANCE, OPERATING, AND SAFETY INFORMATION/INSTRUCTIONS. INSTALL GUIDE SHOULD BE READ AND RETAINED. GREEN LED BLINKS EVERY 10 SECONDS - NORMAL (STANDBY), HORN OFF. RED LED BLINKS EVERY 1 SECOND - SMOKE ALARM, HORN TEMPORAL PATTERN. RED LED BLINKS EVERY 45 SECONDS - LOW BATTERY, HORN CHIRPS EVERY 45 SECONDS LED BLINKS FOR 7 DAYS. **MAINTENANCE NOTE:** POWER MUST BE REMOVED FROM THE DETECTOR BEFORE PERFORMING MAINTENANCE OF ANY KIND BY REMOVING THE DETECTOR'S BATTERY. TEST THE DETECTOR AFTER INSTALLATION, WEEKLY AND AFTER CLEANING (VACUUMING) TO CHECK ALARM FUNCTIONS. THIS ALARM CAN ONLY BE USED WITH SILENT CALL MR1214-MC RECEIVERS. THE BATTERY WARRANTY PERIOD IS NOT A PERFORMANCE CLAIM OF THIS DETECTOR. FOR WARRANTY CLAIMS/REPAIRS SEND TO MANUFACTURER:
SILENT CALL COMMUNICATIONS 5095 WILLIAMS LAKE RD, WATERFORD, MI 48329
CALL 800-572-5227 OR VISIT SILENTCALL.COM

MODEL NO. SD4-MC PHOTO-ELECTRONIC DETECTION PRINCIPLE
IC: 4498A-SD4418SC 418MHz WIRELESS SINGLE STATION SMOKE ALARM
FACTORY SENS. 1.12%-3.33% PER FT. OBSCURATION 85DB SOUNDER

WARNING: USE ONLY BATTERIES SPECIFIED IN MARKING. USE OF A DIFFERENT BATTERY WILL HAVE A DETRIMENTAL EFFECT ON THE SMOKE ALARM OPERATION. REPLACEMENT BATTERY USE PANASONIC CR123A / DURACELL DL123A ONLY. CONSTANT EXPOSURES TO HIGH OR LOW TEMPERATURES OR HIGH HUMIDITY MAY REDUCE BATTERY LIFE. REFER TO INSTALL GUIDE 108125 FOR INSTALLATION, MAINTENANCE, OPERATING, AND SAFETY INFORMATION/INSTRUCTIONS. INSTALL GUIDE SHOULD BE READ AND RETAINED. GREEN LED BLINKS EVERY 10 SECONDS - NORMAL (STANDBY), HORN OFF. RED LED BLINKS EVERY 1 SECOND - SMOKE ALARM, HORN TEMPORAL PATTERN. RED LED BLINKS EVERY 45 SECONDS - LOW BATTERY, HORN CHIRPS EVERY 45 SECONDS LED BLINKS FOR 7 DAYS. MAINTENANCE NOTE: POWER MUST BE REMOVED FROM THE DETECTOR BEFORE PERFORMING MAINTENANCE OF ANY KIND BY REMOVING THE DETECTOR'S BATTERY. TEST THE DETECTOR AFTER INSTALLATION, WEEKLY AND AFTER CLEANING (VACUUMING) TO CHECK ALARM FUNCTIONS. THIS ALARM CAN ONLY BE USED WITH SILENT CALL MR1110-MC RECEIVERS. THE BATTERY WARRANTY PERIOD IS NOT A PERFORMANCE CLAIM OF THIS DETECTOR FOR WARRANTY CLAIMS/REPAIRS SEND TO MANUFACTURER:
SILENT CALL COMMUNICATIONS 5095 WILLIAMS LAKE RD, WATERFORD, MI 48329
CALL 800-572-5227 OR VISIT SILENTCALL.COM

MODÈLE NO. SD4-MC PRINCIPE DE DÉTECTION PHOTO-ÉLECTRONIQUE
IC: 4498A-SD4418SC 418MHz DÉTECTEUR DE FUMÉE SANS FIL À UNE SEULE
STATION FACTORY SENS. USINE. 1.12%-3.33% PAR PIED. OBSCURATION INTEN-
SITE SONORE 85DB

AVERTISSEMENT: N'UTILISEZ QUE LES BATTERIES SPÉCIFIÉES
DANS LA NOTICE. L'UTILISATION D'AUTRES
BATTERIES POURRAIT NUIRE AU FONCTIONNEMENT DE L'ALARME. **UTILISEZ UNE
PILE DE RECHANGE PANASONIC CR123A OU DURACELL DL123A UNIQUEMENT.**

UNE EXPOSITION CONSTANTE À DES TEMPÉRATURES BASSES OU ÉLEVÉES OU
À UNE FORTE HUMIDITÉ PEUT RÉDUIRE LA DURÉE DE VIE DE LA PILE. VEUILLEZ
VOUS REPORTER AU GUIDE D'INSTALLATION 108125 POUR LES INSTRUCTIONS
D'INSTALLATION, DE MAINTENANCE, ET AUTRES INFORMATIONS. VEUILLEZ LIRE ET
CONSERVER LE GUIDE D'INSTALLATION. LE VOYANT DEL VERT CLIGNOTE TOUTES
LES 10 SECONDES - NORMAL (ATTENTE), SON ÉTEINT. LE VOYANT DEL ROUGE
CLIGNOTE TOUTES LES SECONDES - ALARME DE DÉTECTION DE CO, SÉQUENCE
SONORE 4. LE VOYANT DEL ROUGE CLIGNOTE TOUTES LES 45 SECONDES - PILE
PRESQUE ÉPUISÉE, LE DÉTECTEUR ÉMET UN BIP TOUTES LES 45 SECONDES, LE
DEL CLIGNOTE PENDANT 7 JOURS. REMARQUE RELATIVE À LA MAINTENANCE:
LE DÉTECTEUR DOIT ÊTRE MIS HORS TENSION AVANT DE PROCÉDER À TOUTE
OPÉRATION DE **MAINTENANCE**, EN RETIRANT LA PILE DU DÉTECTEUR. TESTEZ
LE DÉTECTEUR DE CO APRES L'INSTALLATION, TOUTES LES SEMAINES, ET APRES
LE NETTOYAGE (ASPIRATEUR) POUR VÉRIFIER LES FONCTIONS D'ALARME. CETTE
ALARME NE PEUT ÊTRE UTILISÉE QU'AVEC DES RÉCEPTEURS SILENT CALL MR-
1110-MC. LE DÉLAI DE GARANTIE DE LA PILE N'EST PAS UNE GARANTIE DE CE
DÉTECTEUR.

MODÈLE NO. SD4-MC PRINCIPE DE DÉTECTION PHOTO-ÉLECTRONIQUE
IC: 4498ASD4418SC 418MHz DÉTECTEUR DE FUMÉE SANS FIL À UNE SEULE
STATION FACTORY SENS. USINE. 1.0% - 4.0% PAR PIED. OBSCURATION INTEN-
SITE SONORE 85DB

AVERTISSEMENT: N'UTILISEZ QUE LES BATTERIES SPÉCIFIÉES
DANS LA NOTICE. L'UTILISATION D'AUTRES
BATTERIES POURRAIT NUIRE AU FONCTIONNEMENT DE L'ALARME. UTILISEZ UNE
PILE DE RECHANGE PANASONIC CR123A OU DURACELL DL123A UNIQUEMENT.
UNE EXPOSITION CONSTANTE À DES TEMPÉRATURES BASSES OU ÉLEVÉES OU
À UNE FORTE HUMIDITÉ PEUT RÉDUIRE LA DURÉE DE VIE DE LA PILE. VEUILLEZ
VOUS REPORTER AU GUIDE D'INSTALLATION 108125 POUR LES INSTRUCTIONS
D'INSTALLATION, DE MAINTENANCE, ET AUTRES INFORMATIONS. VEUILLEZ LIRE ET
CONSERVER LE GUIDE D'INSTALLATION. LE VOYANT DEL VERT CLIGNOTE TOUTES
LES 10 SECONDES - NORMAL (ATTENTE), SON ÉTEINT. LE VOYANT DEL ROUGE
CLIGNOTE TOUTES LES SECONDES - ALARME DE DÉTECTION DE CO. SÉQUENCE
SONORE 4. LE VOYANT DEL ROUGE CLIGNOTE TOUTES LES 45 SECONDES - PILE
PRESQUE ÉPUISÉE. LE DÉTECTEUR ÉMET UN BIP TOUTES LES 45 SECONDES. LE
DEL CLIGNOTE PENDANT 7 JOURS. REMARQUE RELATIVE À LA MAINTENANCE:
LE DÉTECTEUR DOIT ÊTRE MIS HORS TENSION AVANT DE PROCÉDER À TOUTE
OPÉRATION DE MAINTENANCE. EN RETIRANT LA PILE DU DÉTECTEUR, TESTEZ LE
DÉTECTEUR DE CO APRÈS L'INSTALLATION, TOUTES LES SEMAINES, ET APRÈS LE
NETTOYAGE (ASPIRATEUR) POUR VÉRIFIER LES FONCTIONS D'ALARME. CETTE
ALARME NE PEUT ÊTRE UTILISÉE QU'AVEC DES RÉCEPTEURS SILENT CALL MR-
1110-MC. LE DÉLAI DE GARANTIE DE LA PILE N'EST PAS UNE GARANTIE DE CE
DÉTECTEUR.

501
L00-239





Intertek
3126052

CERTIFIED TO
CAN/ULC
STD S531

MODEL NO. SD4-MC PHOTO-ELECTRONIC DETECTION PRINCIPLE
IC: 4498ASD4418SC 418MHz WIRELESS SINGLE STATION SMOKE ALARM
FACTORY SENS. 1.0%- 4.0% PER FT. OBSCURATION 85DB SOUNDER

WARNING: USE ONLY BATTERIES SPECIFIED IN MARKING. USE OF
A DIFFERENT BATTERY WILL HAVE A DETRIMENTAL
EFFECT ON THE SMOKE ALARM OPERATION. REPLACEMENT BATTERY USE PANA-
SONIC CR123A/DURACELL DL123A ONLY. CONSTANT EXPOSURES TO HIGH OR LOW
TEMPERATURES OR HIGH HUMIDITY MAY REDUCE BATTERY LIFE. REFER TO IN-
STALL GUIDE 108125 FOR INSTALLATION, MAINTENANCE, OPERATING, AND SAFETY
INFORMATION/INSTRUCTIONS. INSTALL GUIDE SHOULD BE READ AND RETAINED.
GREEN LED BLINKS EVERY 10 SECONDS - NORMAL (STANDBY), HORN OFF. RED LED
BLINKS EVERY 1 SECOND - SMOKE ALARM, HORN TEMPORAL PATTERN. RED LED
BLINKS EVERY 45 SECONDS - LOW BATTERY, HORN CHIRPS EVERY 45 SECONDS
LED BLINKS FOR 7 DAYS. **MAINTENANCE NOTE:** POWER MUST BE REMOVED FROM
THE DETECTOR BEFORE PERFORMING MAINTENANCE OF ANY KIND BY REMOVING
THE DETECTOR'S BATTERY. TEST THE DETECTOR AFTER INSTALLATION, WEEKLY
AND AFTER CLEANING (VACUUMING) TO CHECK ALARM FUNCTIONS. THIS ALARM
CAN ONLY BE USED WITH SILENT CALL MR1110-MC RECEIVERS. THE BATTERY WAR-
RANTY PERIOD IS NOT A PERFORMANCE CLAIM OF THIS DETECTOR.
FOR WARRANTY CLAIMS/REPAIRS SEND TO MANUFACTURER:
SILENT CALL COMMUNICATIONS 5095 WILLIAMS LAKE RD, WATERFORD, MI 48329
CALL 800-572-5227 OR VISIT SILENTCALL.COM

MANUFACTURED
FABRIQUEE
2015/JUL/20



5062 LISTED 100 239 200



CONFORMS TO UL STD 217

Intertek 3126052

MODEL NO. SD4-MC(US) PHOTO-ELECTRONIC DETECTION PRINCIPLE
FCC ID: PPJSD4418SC 418MHZ WIRELESS SINGLE STATION SMOKE ALARM
FACTORY SENS. 1.0%- 4.0% PER FT. OBSCURATION 85DB SOUNDER

WARNING: USE ONLY BATTERIES SPECIFIED IN MARKING. USE OF A DIFFERENT BATTERY WILL HAVE A DETRIMENTAL EFFECT ON THE SMOKE ALARM OPERATION. **REPLACEMENT BATTERY USE PANASONIC CR123A / DURACELL DL123A ONLY.** CONSTANT EXPOSURES TO HIGH OR LOW TEMPERATURES OR HIGH HUMIDITY MAY REDUCE BATTERY LIFE. REFER TO INSTALL GUIDE 108137 FOR INSTALLATION, MAINTENANCE, OPERATING, AND SAFETY INFORMATION/INSTRUCTIONS. INSTALL GUIDE SHOULD BE READ AND RETAINED. GREEN LED BLINKS EVERY 10 SECONDS - NORMAL (STANDBY), HORN OFF. RED LED BLINKS EVERY 1 SECOND - SMOKE ALARM, HORN TEMPORAL PATTERN. RED LED BLINKS EVERY 45 SECONDS - LOW BATTERY, HORN CHIRPS EVERY 45 SECONDS LED BLINKS FOR 7 DAYS. MAINTENANCE NOTE: POWER MUST BE REMOVED FROM THE DETECTOR BEFORE PERFORMING MAINTENANCE OF ANY KIND BY REMOVING THE DETECTOR'S BATTERY. TEST THE DETECTOR AFTER INSTALLATION, WEEKLY AND AFTER CLEANING (VACUUMING) TO CHECK ALARM FUNCTIONS. THIS ALARM CAN ONLY BE USED WITH SILENT CALL MR1214-MC RECEIVERS. THE BATTERY WARRANTY PERIOD IS NOT A PERFORMANCE CLAIM OF THIS DETECTOR. FOR WARRANTY CLAIMS/REPAIRS SEND TO MANUFACTURER: SILENT CALL COMMUNICATIONS 5095 WILLIAMS LAKE RD, WATERFORD, MI 48329 CALL 800-572-5227 OR VISIT SILENTCALL.COM

PULL TO CONNECT BATTERIES

MANUFACTURED FABRIQUEE

2015/JUL/22





5095 Williams Lake Road, Waterford, MI 48329
(800) 572-5227 v/tty (248) 673-7360 fax
Email: sales@silentcall.com
Website: www.silentcall.com

A better way to stay in touch™

January 6, 2016

To whom it may concern,

In regards to the labeling requirements found in CFR 47, Part 15.19, the project being filed with the FCC does not have sufficient room, due to the safety marking requirements of UL2034, and CAN/CSA-6.19.

We request labeling be present in Installation and Operation Manual. As per:
Subpart (5) of part 15.19 (See excerpt below)

(5) When the device is so small or for such use that it is not practicable to place the statement specified under paragraph (a) of this section on it, the information required by this paragraph shall be placed in a prominent location in the instruction manual or pamphlet supplied to the user or, alternatively, shall be placed on the container in which the device is marketed. However, the FCC identifier or the unique identifier, as appropriate, must be displayed on the device.

If you have any other questions or concerns regarding this, or any other matter, please do not hesitate in contacting me.

Best regards,

George Elwell


President